Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	36
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	A	rea: Area	1		
X Coord	Y Coord	Label	Value	Туре	Historical
679530.9430	3082575.4480	G-36SD	0.007	Manual	Т
679606.6840	3082692.3830	G-37SD	0.0029	Manual	Т
679671.3170	3082565.9250	G-46SD	0.0027	Manual	Т
679745.9820	3082681.3860	G-47SD	0.0027	Manual	Т
679532.9930	3082835.5820	J-42SD	0.0085	Manual	Т
679552.9590	3082868.6600	J-43SD	0.0076	Manual	Т
679521.7790	3082672.0220	J-54SD	0.0027	Manual	Т
680108.0130	3083101.3520	J-57SD	0.0106	Manual	Т
680413.8310	3083297.0130	J-58SD	0.0027	Manual	Т
679149.4920	3082933.0980	TW01-13	0.0027	Manual	Т
679279.7760	3083075.6320	TW01-14	0.0027	Manual	Т
679293.5600	3082950.4980	TW01-17	0.0046	Manual	Т
679360.5700	3083026.4980	TW01-18	0.0211	Manual	Т
679169.0760	3082537.3510	TW01-27	0.01665	Manual	Т
679495.8840	3082940.9730	TW01-33	0.0095	Manual	Т
679304.6530	3082548.6880	TW01-34	0.0082	Manual	Т

679342.7410	3082605.3190	TW01-35	0.0195	Manual	Т
679382.8900	3082667.5270	TW01-36	0.0437	Manual	Т
679433.9450	3082731.6820	TW01-37	0.0066	Manual	Т
679470.3570	3082776.7350	TW01-38	0.0105	Manual	Т
679497.3310	3082840.3960	TW01-39	0.0027	Manual	Т
679524.3310	3082886.8990	TW01-40	0.0027	Manual	Т
679560.6110	3082897.2580	TW01-41	0.0075	Manual	Т
679276.8911	3082736.8178	J-59SD	0.0027	Random	

Area: Area 2									
X Coord Y Coord Label Value Type Histori									
680310.3290	3082668.1710	J-59SD	0.0027	Manual	Т				
680352.2560	3082820.3630	J-60SD	0.0027	Manual	Т				
680379.4090	3082937.1350	J-61SD	0.0027	Manual	Т				

Area: Area 3									
X Coord Y Coord Label Value Type Historic									
679386.3850	3083044.5490	TW06-63	0.0031	Manual	Т				
679396.8510	679396.8510 3083038.0640 TW06-64 0.0027 Manual								

Area: Area 4								
X Coord	Y Coord	Label	Value	Туре	Historical			

	Area: Area 5										
X Coord	Y Coord	Label	Value	Туре	Historical						
679133.4290	3083306.3130	TW01-01	0.0027	Manual	Т						
679104.2450	3083223.2620	TW01-02	0.0028	Manual	Т						
679242.7260	3083326.5280	TW01-07	0.0027	Manual	Т						
679181.2750	3083178.2880	TW01-08	0.0038	Manual	Т						
679268.7700	3083200.3260	TW01-11	0.0035	Manual	Т						
679301.1600	3083254.0340	TW01-12	0.0027	Manual	Т						
679322.2873	3083277.3101		0	Random							

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta				Para	ameter		
Analyte	n	S	Z _{1-β} b				
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples										
A1 -0.4	10	α=	:5	α=	:10	α=	15				
AL=0.19		s=6	s=3	s=6	s=3	s=6	s=3				
	β=5	1079221	269807	854014	213504	716940	179236				
LBGR=90	β=10	854014	213505	655131	163784	535818	133955				
	β=15	716940	179236	535818	133956	428488	107123				
	β=5	269807	67453	213504	53377	179236	44810				
LBGR=80	β=10	213505	53378	163784	40947	133955	33490				
	β=15	179236	44811	133956	33490	107123	26782				
LBGR=70	β=5	119915	29980	94892	23724	79661	19916				

β=10	94892	23724	72794	18199	59536	14885
β=15	79662	19917	59537	14885	47611	11903

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details Per Analysis Per Sample 21 Sai									
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027
10	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0028	0.0029
20	0.0031	0.0031	0.0035	0.0038	0.0046	0.0066	0.007	0.0075	0.0076	0.0082
30	0.0085	0.0095	0.0105	0.0106	0.01665	0.0195	0.0211	0.0437		

SUMMARY STATISTICS			
n	38		
Min	0		
Max	0.0437		
Range	0.0437		
Mean 0.0064908			
Median	0.00285		
Variance	6.1556e-005		
StdDev	0.0078458		
Std Error	0.0012728		
Skewness	3.3454		
Interquartile Range	0.00505		
Percentiles			

1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.002565	0.0027	0.0027	0.00285	0.00775	0.01694	0.02223	0.0437

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	4.743	3.01	Yes			

The test statistic 4.743 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	0.0437	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Shapiro-Wilk Test Statistic	0.7026		
Shapiro-Wilk 5% Critical Value	0.936		

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted

individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5919			
Shapiro-Wilk 5% Critical Value	0.938			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance.

The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.008638			
95% Non-Parametric (Chebyshev) UCL	0.01204			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.01204) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=38 data,

AL is the action level or threshold (0.19),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=37 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
-144.18	1.6871	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
38	24	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	36
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679530.9430	3082575.4480	G-36SD	0.007	Manual	Т	
679606.6840	3082692.3830	G-37SD	0.0029	Manual	Т	
679671.3170	3082565.9250	G-46SD	0.0027	Manual	Т	
679745.9820	3082681.3860	G-47SD	0.0027	Manual	Т	
679532.9930	3082835.5820	J-42SD	0.0085	Manual	Т	
679552.9590	3082868.6600	J-43SD	0.0076	Manual	Т	
679521.7790	3082672.0220	J-54SD	0.0027	Manual	Т	
680108.0130	3083101.3520	J-57SD	0.0106	Manual	Т	
680413.8310	3083297.0130	J-58SD	0.0027	Manual	Т	
679149.4920	3082933.0980	TW01-13	0.0027	Manual	Т	
679279.7760	3083075.6320	TW01-14	0.0027	Manual	Т	
679293.5600	3082950.4980	TW01-17	0.0046	Manual	Т	
679360.5700	3083026.4980	TW01-18	0.0211	Manual	Т	
679169.0760	3082537.3510	TW01-27	0.01665	Manual	Т	
679495.8840	3082940.9730	TW01-33	0.0095	Manual	Т	
679304.6530	3082548.6880	TW01-34	0.0082	Manual	Т	

679342.7410	3082605.3190	TW01-35	0.0195	Manual	Т
679382.8900	3082667.5270	TW01-36	0.0437	Manual	Т
679433.9450	3082731.6820	TW01-37	0.0066	Manual	Т
679470.3570	3082776.7350	TW01-38	0.0105	Manual	Т
679497.3310	3082840.3960	TW01-39	0.0027	Manual	Т
679524.3310	3082886.8990	TW01-40	0.0027	Manual	Т
679560.6110	3082897.2580	TW01-41	0.0075	Manual	Т

Area: Area 2									
X Coord	Y Coord	Value	Туре	Historical					
680310.3290	3082668.1710	J-59SD	0.0027	Manual	Т				
680352.2560	3082820.3630	J-60SD	0.0027	Manual	Т				
680379.4090	3082937.1350	J-61SD	0.0027	Manual	Т				

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679386.3850	3083044.5490	TW06-63	0.0031	Manual	Т			
679396.8510	3083038.0640	TW06-64	0.0027	Manual	Т			

Area: Area 4							
X Coord	X Coord Y Coord Label Value Type Historical						
679084.9690	3083201.1536	TW01-01	0.0027	Random			

	Area: Area 5									
X Coord	Y Coord	Label	Value	Туре	Historical					
679133.4290	3083306.3130	TW01-01	0.0027	Manual	Т					
679104.2450	3083223.2620	TW01-02	0.0028	Manual	Т					
679242.7260	3083326.5280	TW01-07	0.0027	Manual	Т					
679181.2750	3083178.2880	TW01-08	0.0038	Manual	Т					
679268.7700	3083200.3260	TW01-11	0.0035	Manual	Т					
679301.1600	3083254.0340	TW01-12	0.0027	Manual	Т					
679126.0114	3083278.9929		0	Random						

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
A1 -0.0	70	α=	=5	α=	:10	α=	15	
AL=0.0	10	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	6403655	1600915	5067367	1266843	4254025	1063507	
LBGR=90	β=10	5067367	1266843	3887278	971821	3179323	794832	
	β=15	4254026	1063508	3179323	794832	2542472	635619	
	β=5	1600915	400230	1266843	316712	1063507	265878	
LBGR=80	β=10	1266843	316712	971821	242956	794832	198709	
	β=15	1063508	265878	794832	198709	635619	158906	
LBGR=70	β=5	711519	177881	563042	140761	472670	118168	

β=10	563042	140762	431921	107981	353259	88316
β=15	472671	118169	353259	88316	282498	70625

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027
10	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0028	0.0029
20	0.0031	0.0031	0.0035	0.0038	0.0046	0.0066	0.007	0.0075	0.0076	0.0082
30	0.0085	0.0095	0.0105	0.0106	0.01665	0.0195	0.0211	0.0437		

SUMMARY ST	ATISTICS					
n	38					
Min	0					
Max	0.0437					
Range	0.0437					
Mean	0.0064908					
Median	0.00285					
Variance	6.1556e-005					
StdDev	0.0078458					
Std Error	0.0012728					
Skewness	3.3454					
Interquartile Range 0.00505						
Percentiles						

1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.002565	0.0027	0.0027	0.00285	0.00775	0.01694	0.02223	0.0437

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST								
	k	Test Statistic R _k	5% Critical Value C _k	Significant?				
	1	4.743	3.01	Yes				

The test statistic 4.743 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	0.0437		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Shapiro-Wilk Test Statistic 0.7026				
Shapiro-Wilk 5% Critical Value 0.936				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted

individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic 0.5919				
Shapiro-Wilk 5% Critical Value	0.938			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance.

The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL 0.008638				
95% Non-Parametric (Chebyshev) UCL	0.01204			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.01204) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=38 data,

AL is the action level or threshold (0.078),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=37 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-56.185	1.6871	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
38	24	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	2				
Number of samples on map ^a	35				
Number of selected sample areas b	5				
Specified sampling area ^c	941426.62 m ²				
Total cost of sampling ^d	\$2,000.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679530.9430	3082575.4480	G-36SD	0.007	Manual	Т	
679606.6840	3082692.3830	G-37SD	0.0029	Manual	Т	
679671.3170	3082565.9250	G-46SD	0.0027	Manual	Т	
679745.9820	3082681.3860	G-47SD	0.0027	Manual	Т	
679532.9930	3082835.5820	J-42SD	0.0085	Manual	Т	
679552.9590	3082868.6600	J-43SD	0.0076	Manual	Т	
679521.7790	3082672.0220	J-54SD	0.0027	Manual	Т	
680108.0130	3083101.3520	J-57SD	0.0106	Manual	Т	
680413.8310	3083297.0130	J-58SD	0.0027	Manual	Т	
679149.4920	3082933.0980	TW01-13	0.0027	Manual	Т	
679279.7760	3083075.6320	TW01-14	0.0027	Manual	Т	
679293.5600	3082950.4980	TW01-17	0.0046	Manual	Т	
679360.5700	3083026.4980	TW01-18	0.0211	Manual	Т	
679169.0760	3082537.3510	TW01-27	0.01665	Manual	Т	
679495.8840	3082940.9730	TW01-33	0.0095	Manual	Т	
679304.6530	3082548.6880	TW01-34	0.0082	Manual	Т	

679342.7410	3082605.3190	TW01-35	0.0195	Manual	Т
679382.8900	3082667.5270	TW01-36	0.0437	Manual	Т
679433.9450	3082731.6820	TW01-37	0.0066	Manual	Т
679470.3570	3082776.7350	TW01-38	0.0105	Manual	Т
679497.3310	3082840.3960	TW01-39	0.0027	Manual	Т
679524.3310	3082886.8990	TW01-40	0.0027	Manual	Т
679560.6110	3082897.2580	TW01-41	0.0075	Manual	Т
679431.2599	3082589.5638		0	Random	

Area: Area 2					
X Coord Y Coord Label Value Type					Historical
680310.3290	3082668.1710	J-59SD	0.0027	Manual	Т
680352.2560	3082820.3630	J-60SD	0.0027	Manual	Т
680379.4090	3082937.1350	J-61SD	0.0027	Manual	Т

Area: Area 3					
X Coord Y Coord Label Value Type Histor					Historical
679386.3850	3083044.5490	TW06-63	0.0031	Manual	Т
679396.8510	3083038.0640	TW06-64	0.0027	Manual	Т

Area: Area 4					
X Coord	Y Coord	Label	Value	Туре	Historical

Area: Area 5							
X Coord	Y Coord	Label	Value	Туре	Historical		
679133.4290	3083306.3130	TW01-01	0.0027	Manual	Т		
679104.2450	3083223.2620	TW01-02	0.0028	Manual	Т		
679242.7260	3083326.5280	TW01-07	0.0027	Manual	Т		
679181.2750	3083178.2880	TW01-08	0.0038	Manual	Т		
679268.7700	3083200.3260	TW01-11	0.0035	Manual	Т		
679301.1600	3083254.0340	TW01-12	0.0027	Manual	Т		

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than

the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_						
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	2	0.0080184	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples							
AL=4.5e-005		α	=5	α=	:10	α=15		
		s=0.0160368	s=0.0080184	s=0.0160368	s=0.0080184	s=0.0160368	s=0.0080184	
	β=5	137443723	34360932	108762535	27190635	91305516	22826380	
LBGR=90	β=10	108762535	27190635	83433904	20858477	68238839	17059711	
	β=15	91305517	22826381	68238840	17059711	54569904	13642477	
	β=5	34360932	8590234	27190635	6797660	22826380	5706596	
LBGR=80	β=10	27190635	6797660	20858477	5214620	17059711	4264928	
	β=15	22826381	5706597	17059711	4264929	13642477	3410620	
LBGR=70	β=5	15271526	3817883	12084727	3021183	10145058	2536265	

β=10	12084728	3021183	9270435	2317610	7582094	1895524
β=15	10145059	2536266	7582094	1895525	6063324	1515832

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$2,000.00, which averages out to a per sample cost of \$1,000.00. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	2 Samples				
Field collection costs		\$100.00	\$200.00				
Analytical costs	\$400.00	\$400.00	\$800.00				
Sum of Field & Analytical costs		\$500.00	\$1,000.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$2,000.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027
10	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0028	0.0029
20	0.0031	0.0035	0.0038	0.0046	0.0066	0.007	0.0075	0.0076	0.0082	0.0085
30	0.0095	0.0105	0.0106	0.01665	0.0195	0.0211	0.0437			

SUMMARY STATISTICS				
n	37			
Min	0			
Max	0.0437			
Range 0.0437				
Mean	0.0065824			
Median	0.0028			
Variance	6.2938e-005			
StdDev	0.0079334			
Std Error	0.0013042			
Skewness	3.2964			
Interquartile Range	0.0052			
Percentiles				

1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.00243	0.0027	0.0027	0.0028	0.0079	0.01722	0.02336	0.0437

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
	k	Test Statistic R _k	5% Critical Value C _k	Significant?		
	1	4.616	2.99	Yes		

The test statistic 4.616 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	0.0437		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION T	EST (excluding outliers)
Shapiro-Wilk Test Statistic	0.7187
Shapiro-Wilk 5% Critical Value	0.934

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted

individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Shapiro-Wilk Test Statistic	0.5979			
Shapiro-Wilk 5% Critical Value	0.936			

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance.

The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.008784				
95% Non-Parametric (Chebyshev) UCL	0.01227				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.01227) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=37 data,

AL is the action level or threshold (4.5e-005),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=36 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value t _{0.95} Null Hypothesis						
5.0125	1.6883	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
1	23	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	36
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679530.9430	3082575.4480	G-36SD	0.007	Manual	Т				
679606.6840	3082692.3830	G-37SD	0.0029	Manual	Т				
679671.3170	3082565.9250	G-46SD	0.0027	Manual	Т				
679745.9820	3082681.3860	G-47SD	0.0027	Manual	Т				
679532.9930	3082835.5820	J-42SD	0.0085	Manual	Т				
679552.9590	3082868.6600	J-43SD	0.0076	Manual	Т				
679521.7790	3082672.0220	J-54SD	0.0027	Manual	Т				
680108.0130	3083101.3520	J-57SD	0.0106	Manual	Т				
680413.8310	3083297.0130	J-58SD	0.0027	Manual	Т				
679149.4920	3082933.0980	TW01-13	0.0027	Manual	Т				
679279.7760	3083075.6320	TW01-14	0.0027	Manual	Т				
679293.5600	3082950.4980	TW01-17	0.0046	Manual	Т				
679360.5700	3083026.4980	TW01-18	0.0211	Manual	Т				
679169.0760	3082537.3510	TW01-27	0.01665	Manual	Т				
679495.8840	3082940.9730	TW01-33	0.0095	Manual	Т				
679304.6530	3082548.6880	TW01-34	0.0082	Manual	Т				

679342.7410	3082605.3190	TW01-35	0.0195	Manual	Т
679382.8900	3082667.5270	TW01-36	0.0437	Manual	Т
679433.9450	3082731.6820	TW01-37	0.0066	Manual	Т
679470.3570	3082776.7350	TW01-38	0.0105	Manual	Т
679497.3310	3082840.3960	TW01-39	0.0027	Manual	Т
679524.3310	3082886.8990	TW01-40	0.0027	Manual	Т
679560.6110	3082897.2580	TW01-41	0.0075	Manual	Т

Area: Area 2									
X Coord	Y Coord	Label	Value	Туре	Historical				
680310.3290	3082668.1710	J-59SD	0.0027	Manual	Т				
680352.2560	3082820.3630	J-60SD	0.0027	Manual	Т				
680379.4090	3082937.1350	J-61SD	0.0027	Manual	Т				

Area: Area 3									
X Coord	Historical								
679386.3850	3083044.5490	TW06-63	0.0031	Manual	Т				
679396.8510	3083038.0640	TW06-64	0.0027	Manual	Т				
679401.5543	3083034.8156	TW01-01	0.0027	Random					

Area: Area 4						
X Coord	Y Coord	Label	Value	Туре	Historical	

Area: Area 5									
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	TW01-01	0.0027	Manual	Т				
679104.2450	3083223.2620	TW01-02	0.0028	Manual	Т				
679242.7260	3083326.5280	TW01-07	0.0027	Manual	Т				
679181.2750	3083178.2880	TW01-08	0.0038	Manual	Т				
679268.7700	3083200.3260	TW01-11	0.0035	Manual	Т				
679301.1600	3083254.0340	TW01-12	0.0027	Manual	Т				
679202.5111	3083224.7611		0	Random					

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
AL=0.01		α=	:5	α=′	10	α=15			
AL=0.0	, 1	s=6 s=3		s=6 s=3		s=6	s=3		
	β=5	389598259	97399566	308298506	77074627	258814803	64703702		
LBGR=90	β=10	308298506	77074628	236501917	59125480	193429954	48357489		
	β=15	258814804	64703702	193429954	48357490	154683962	38670991		
	β=5	97399566	24349893	77074627	19268658	64703702	16175926		
LBGR=80	β=10	77074628	19268658	59125480	14781371	48357489	12089373		
	β=15	64703702	16175927	48357490	12089373	38670991	9667749		
LBGR=70	β=5	43288697	10822176	34255391	8563849	28757201	7189301		

β=10	34255391	8563849	26277992	6569499	21492218	5373055
β=15	28757202	7189302	21492218	5373056	17187108	4296778

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027
10	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0027	0.0028	0.0029
20	0.0031	0.0031	0.0035	0.0038	0.0046	0.0066	0.007	0.0075	0.0076	0.0082
30	0.0085	0.0095	0.0105	0.0106	0.01665	0.0195	0.0211	0.0437		

SUMMARY STATISTICS				
n	38			
Min	0			
Max	0.0437			
Range	0.0437			
Mean	0.0064908			
Median	0.00285			
Variance	6.1556e-005			
StdDev	0.0078458			
Std Error	0.0012728			
Skewness	3.3454			
Interquartile Range	0.00505			
Percentiles				

19	6 5%	10%	25%	50%	75%	90%	95%	99%
0	0.002565	0.0027	0.0027	0.00285	0.00775	0.01694	0.02223	0.0437

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	4.68	3	Yes			

The test statistic 4.68 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	0.0437		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7114				
Shapiro-Wilk 5% Critical Value	0.935				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted

individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic	0.5919				
Shapiro-Wilk 5% Critical Value	0.938				

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance.

The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.008638			
95% Non-Parametric (Chebyshev) UCL	0.01204			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.01204) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=38 data,

AL is the action level or threshold (0.01),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=37 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value t _{0.95} Null Hypothesis					
-2.7572	1.6871	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
32	24	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	36
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Ar	ea: Area 1			
X Coord	Y Coord	Label	Value	Туре	Historical
679530.9430	3082575.4480	G-36SD	7	Manual	Т
679606.6840	3082692.3830	G-37SD	2.9	Manual	Т
679671.3170	3082565.9250	G-46SD	1.35	Manual	Т
679745.9820	3082681.3860	G-47SD	1.35	Manual	Т
679532.9930	3082835.5820	J-42SD	8.5	Manual	Т
679552.9590	3082868.6600	J-43SD	7.6	Manual	Т
679521.7790	3082672.0220	J-54SD	1.35	Manual	Т
680108.0130	3083101.3520	J-57SD	10.6	Manual	Т
680413.8310	3083297.0130	J-58SD	1.35	Manual	Т
679149.4920	3082933.0980	TW01-13	1.35	Manual	Т
679279.7760	3083075.6320	TW01-14	2.7	Manual	Т
679293.5600	3082950.4980	TW01-17	4.6	Manual	Т
679360.5700	3083026.4980	TW01-18	21.1	Manual	Т
679169.0760	3082537.3510	TW01-27	16.65	Manual	Т
679495.8840	3082940.9730	TW01-33	9.5	Manual	Т
679304.6530	3082548.6880	TW01-34	8.2	Manual	Т

679342.7410	3082605.3190	TW01-35	19.5	Manual	Т
679382.8900	3082667.5270	TW01-36	43.7	Manual	Т
679433.9450	3082731.6820	TW01-37	6.6	Manual	Т
679470.3570	3082776.7350	TW01-38	10.5	Manual	Т
679497.3310	3082840.3960	TW01-39	1.35	Manual	Т
679524.3310	3082886.8990	TW01-40	1.35	Manual	Т
679560.6110	3082897.2580	TW01-41	7.5	Manual	Т

Area: Area 2									
X Coord Y Coord Label Value Type History									
680310.3290	3082668.1710	J-59SD	1.35	Manual	Т				
680352.2560	3082820.3630	J-60SD	1.35	Manual	Т				
680379.4090	3082937.1350	J-61SD	1.35	Manual	Т				

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679386.3850	3083044.5490	TW06-63	3.1	Manual	Т				
679396.8510	3083038.0640	TW06-64	1.35	Manual	Т				
679404.4014	3083030.3745	TW01-01	1.35	Random					

Area: Area 4							
X Coord	Y Coord	Label	Value	Туре	Historical		

	Area: Area 5										
X Coord	Y Coord	Label	Value	Туре	Historical						
679133.4290	3083306.3130	TW01-01	1.35	Manual	Т						
679104.2450	3083223.2620	TW01-02	2.8	Manual	Т						
679242.7260	3083326.5280	TW01-07	1.35	Manual	Т						
679181.2750	3083178.2880	TW01-08	3.8	Manual	Т						
679268.7700	3083200.3260	TW01-11	3.5	Manual	Т						
679301.1600	3083254.0340	TW01-12	1.35	Manual	Т						
679289.1671	3083299.2675		0	Random							

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte	_				Para	ameter	
	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=10		α=5		α=10		α=15		
		s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	391	99	310	78	260	66	
LBGR=90	β=10	310	79	238	60	194	49	
	β=15	261	67	195	50	156	40	
	β=5	99	26	78	21	66	17	
LBGR=80	β=10	79	21	60	16	49	13	
	β=15	67	18	50	13	40	11	
LBGR=70	β=5	45	13	36	10	30	8	

β=10	36	10	28	8	23	6
β=15	31	9	23	7	18	5

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	1.35	1.35	1.35	1.35	1.35	1.35	1.35	1.35	1.35
10	1.35	1.35	1.35	1.35	1.35	1.35	2.7	2.8	2.9	3.1
20	3.5	3.8	4.6	6.6	7	7.5	7.6	8.2	8.5	9.5
30	10.5	10.6	16.65	19.5	21.1	43.7				

SUMMARY ST	SUMMARY STATISTICS			
n	36			
Min	0			
Max	43.7			
Range	43.7			
Mean	6.1278			
Median	2.85			
Variance	69.367			
StdDev	8.3287			
Std Error	1.3881			
Skewness	3.0451			
Interquartile Range	6.7			
Percent	Percentiles			

1%	5%	10%	25%	50%	75%	90%	95%	99%
0	1.148	1.35	1.35	2.85	8.05	17.5	24.49	43.7

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	4.401	2.97	Yes		

The test statistic 4.401 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	43.7	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)		
Shapiro-Wilk Test Statistic	0.7543	
Shapiro-Wilk 5% Critical Value	0.931	

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted

individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Shapiro-Wilk Test Statistic	0.6436		
Shapiro-Wilk 5% Critical Value	0.935		

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance.

The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN			
95% Parametric UCL	8.473		
95% Non-Parametric (Chebyshev) UCL	12.18		

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (12.18) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=36 data,

AL is the action level or threshold (10),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=35 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic	Critical Value t _{0.95}	Null Hypothesis	
-2.7896	1.6896	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
30	23	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	36
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679530.9430	3082575.4480	G-36SD	361000	Manual	Т	
679606.6840	3082692.3830	G-37SD	222000	Manual	Т	
679671.3170	3082565.9250	G-46SD	238000	Manual	Т	
679745.9820	3082681.3860	G-47SD	235000	Manual	Т	
679532.9930	3082835.5820	J-42SD	192000	Manual	Т	
679552.9590	3082868.6600	J-43SD	216000	Manual	Т	
679521.7790	3082672.0220	J-54SD	242500	Manual	Т	
680108.0130	3083101.3520	J-57SD	417000	Manual	Т	
680413.8310	3083297.0130	J-58SD	882000	Manual	Т	
679149.4920	3082933.0980	TW01-13	42700	Manual	Т	
679279.7760	3083075.6320	TW01-14	13300	Manual	Т	
679293.5600	3082950.4980	TW01-17	26100	Manual	Т	
679360.5700	3083026.4980	TW01-18	26500	Manual	Т	
679169.0760	3082537.3510	TW01-27	54050	Manual	Т	
679495.8840	3082940.9730	TW01-33	58100	Manual	Т	
679304.6530	3082548.6880	TW01-34	1.45e+006	Manual	Т	

679342.7410	3082605.3190	TW01-35	124000	Manual	Т
679382.8900	3082667.5270	TW01-36	130000	Manual	Т
679433.9450	3082731.6820	TW01-37	603000	Manual	Т
679470.3570	3082776.7350	TW01-38	343000	Manual	Т
679497.3310	3082840.3960	TW01-39	304000	Manual	Т
679524.3310	3082886.8990	TW01-40	285000	Manual	Т
679560.6110	3082897.2580	TW01-41	216000	Manual	Т
680138.4983	3083329.9265	J-59SD	1.2e+006	Random	

Area: Area 2								
X Coord	Y Coord	Label	Value	Туре	Historical			
680310.3290	3082668.1710	J-59SD	1.2e+006	Manual	Т			
680352.2560	3082820.3630	J-60SD	1.165e+006	Manual	Т			
680379.4090	3082937.1350	J-61SD	1.18e+006	Manual	Т			
680354.4110	3082691.5331	TW06-63	15800	Random				

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679386.3850	3083044.5490	TW06-63	15800	Manual	Т			
679396.8510	3083038.0640	TW06-64	21700	Manual	Т			

Area: Area 4						
X Coord	Y Coord	Label	Value	Туре	Historical	

Area: Area 5									
X Coord	Y Coord	Label	Value	Туре	Historical				
679133.4290	3083306.3130	TW01-01	3820	Manual	Т				
679104.2450	3083223.2620	TW01-02	6800	Manual	Т				
679242.7260	3083326.5280	TW01-07	7770	Manual	Т				
679181.2750	3083178.2880	TW01-08	23600	Manual	Т				
679268.7700	3083200.3260	TW01-11	10300	Manual	Т				
679301.1600	3083254.0340	TW01-12	8520	Manual	Т				

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric

approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability (1-ß) of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

S Δ α β $Z_{1-\alpha}$ $Z_{1-\beta}$ is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

^b This value is automatically calculated by VSP based upon the user defined value of β.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=3230		α=	=5	α=	:10	α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	2	2	1	1	1 1	
LBGR=90	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
	β=5	2	2	1	1	1	1
LBGR=80	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
LBGR=70	β=5	2	2	1	1	1	1

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	3820	6800	7770	8520	1.03e+004	1.33e+004	1.58e+004	1.58e+004	2.17e+004	2.36e+004
10	2.61e+004	2.65e+004	4.27e+004	5.405e+004	5.81e+004	1.24e+005	1.3e+005	1.92e+005	2.16e+005	2.16e+005
20	2.22e+005	2.35e+005	2.38e+005	2.425e+005	2.85e+005	3.04e+005	3.43e+005	3.61e+005	4.17e+005	6.03e+005
30	8.82e+005	1.165e+006	1.18e+006	1.2e+006	1.2e+006	1.45e+006				

SUMMARY STATISTICS						
n	36					
Min	3820					
Max	1450000					
Range	1.4462e+006					
Mean	3.2057e+005					
Median	204000					
Variance	1.761e+011					
StdDev	4.1965e+005					
Std Error	69941					
Skewness	1.5619					
Interquartile Range	3.3433e+005					
Percentiles						

1%	5%	10%	25%	50%	75%	90%	95%	99%
3820	6353	8295	2.218e+004	2.04e+005	3.565e+005	1.186e+006	1.237e+006	1.45e+006

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	2.864	2.97	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Shapiro-Wilk test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Shapiro-Wilk Test Statistic	0.7187				
Shapiro-Wilk 5% Critical Value	0.931				

The calculated Shapiro-Wilk test statistic is less than the 5% Shapiro-Wilk critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.

Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the

Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Shapiro-Wilk (SW) test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Shapiro-Wilk Test Statistic 0.727					
Shapiro-Wilk 5% Critical Value 0.935					

The calculated SW test statistic is less than the 5% Shapiro-Wilk critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	4.387e+005				
95% Non-Parametric (Chebyshev) UCL	6.254e+005				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (6.254e+005) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=36 data, AL is the action level or threshold (3230),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=35 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
4.5372	1.6896	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
0	23	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	21				
Number of samples on map ^a	60				
Number of selected sample areas b	5				
Specified sampling area ^c	941426.62 m ²				
Total cost of sampling d	\$11,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679149.4920	3082933.0980	J-13S	0.54	Manual	Т	
679279.6830	3083075.4290	J-14S	0.23	Manual	Т	
679261.0980	3083016.3510	J-15S	0.38	Manual	Т	
679222.6340	3082840.1720	J-16S	0.33	Manual	Т	
679293.5600	3082950.4980	J-17S	0.41	Manual	Т	
679360.5700	3083026.4980	J-18S	0.44	Manual	Т	
679343.5810	3082969.5980	J-19S	1.7	Manual	Т	
679382.8640	3083009.1130	J-20S	2.4	Manual	Т	
679335.0020	3082941.1720	J-21S	0.2	Manual	Т	
679252.7130	3082781.0290	J-22S	0.74	Manual	Т	
679297.0010	3082840.6970	J-23S	1.4	Manual	Т	
679394.8070	3082971.8300	J-24S	0.3	Manual	Т	
679146.6460	3082549.7640	J-25S	1	Manual	Т	
679224.5850	3082683.1400	J-26S	0.22	Manual	Т	
679169.0760	3082537.3510	J-27S	1	Manual	Т	
679272.0040	3082652.6750	J-28S	1.2	Manual	Т	

679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679560.6070	3082897.2580	J-41S	1.7	Manual	Т
679924.8150	3082872.3490	J-47S	1.3	Manual	Т
679994.9690	3082983.5100	J-48S	1.2	Manual	Т
680057.6580	3083072.0750	J-49S	0.69	Manual	Т
680077.3540	3083115.5330	J-50S	0.52	Manual	Т
679827.1150	3082729.7460	J-51S	0.63	Manual	Т
680141.8730	3083080.8800	J-52S	1.1	Manual	Т
680170.5600	3083064.6740	J-53S	2.4	Manual	Т
679129.3320	3082802.5620	Composite 1	0.22	Manual	Т
679124.7500	3082617.3010	Composite 3	1.6	Manual	Т
679107.0750	3082512.5600	Composite 4	0.25	Manual	Т
679240.6200	3082579.3320	Composite 2	0.44	Manual	Т
679290.8532	3082833.4033	Composite 5	0.94	Random	

Area: Area 2					
X Coord Y Coord Label Value Type Historica					
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical
679356.9310	3083064.0350	J-62S	0.22	Manual	Т
679396.8510	3083038.0640	J-64S	0.24	Manual	Т
679386.3850	3083044.5490	J-63S	0.35	Manual	Т

Area: Area 4					
X Coord	Y Coord	Label	Value	Туре	Historical
679175.7550	3083152.6270	J-65S	0.85	Manual	Т
679113.1200	3083190.3150	J-66S	0.18	Manual	Т

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т
679204.6866	3083366.2710		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold.

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold.

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{-\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter							Parameter		
Analyte	n	SΔ		α	β	$Z_{1-\alpha}$ a	Z _{1-β} b				
	21	3	2	0.05	0.1	1.64485	1.28155				


^a This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of ß.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30

or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=2.50958		α=	=5	α=	10	α=	α=15	
AL=2.50	1930	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	6188	1548	4897	1225	4111	1028	
LBGR=90	β=10	4897	1226	3757	940	3072	769	
	β=15	4111	1029	3073	769	2457	615	
	β=5	1548	388	1225	307	1028	258	
LBGR=80	β=10	1226	308	940	236	769	193	
	β=15	1029	259	769	193	615	155	
LBGR=70	β=5	689	174	545	137	458	115	
	β=10	546	138	419	106	342	86	
	β=15	458	116	343	87	274	69	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

The following data points were entered by the user for analysis.

Rank 1 2 3	4 5 6	7 8 9 10
------------	-------	----------

0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.22
10	0.23	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28
20	0.28	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44
30	0.47	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74
40	0.78	0.8	0.81	0.85	0.85	0.94	0.94	1	1	1.1
50	1.1	1.2	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1
60	2.2	2.4	2.4							

	SUMMARY STATISTICS							
		63						
	IV	lin				0		
	M	ax				2.4		
	Ra	nge				2.4		
	М	ean			0	.7134	9	
	Ме			0.52				
	Vari	0.35464						
	Std	Dev		0.59552				
	Std	Error		0.075028				
	Skev	vness		1.3367				
Inte	erquar	tile Ra	0.75					
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.18	0.208	0.25	0.52	1	1.7	2.18	2.4

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST					
k	k Test Statistic R _k 5% Critical Value C _k Significant					
1	2.832	3.218	No			

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1573
Lilliefors 5% Critical Value	0.1125

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.1605			
Lilliefors 5% Critical Value	0.1116			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.8388			
95% Non-Parametric (Chebyshev) UCL	1.041			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.041) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (2.50958).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-23.939	1.6698	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
63	39	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	60
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1											
X Coord	Y Coord	Label	Value	Туре	Historical							
679149.4920	3082933.0980	J-13S	0.54	Manual	Т							
679279.6830	3083075.4290	J-14S	0.23	Manual	Т							
679261.0980	3083016.3510	J-15S	0.38	Manual	Т							
679222.6340	3082840.1720	J-16S	0.33	Manual	Т							
679293.5600	3082950.4980	J-17S	0.41	Manual	Т							
679360.5700	3083026.4980	J-18S	0.44	Manual	Т							
679343.5810	3082969.5980	J-19S	1.7	Manual	Т							
679382.8640	3083009.1130	J-20S	2.4	Manual	Т							
679335.0020	3082941.1720	J-21S	0.2	Manual	Т							
679252.7130	3082781.0290	J-22S	0.74	Manual	Т							
679297.0010	3082840.6970	J-23S	1.4	Manual	Т							
679394.8070	3082971.8300	J-24S	0.3	Manual	Т							
679146.6460	3082549.7640	J-25S	1	Manual	Т							
679224.5850	3082683.1400	J-26S	0.22	Manual	Т							
679169.0760	3082537.3510	J-27S	1	Manual	Т							
679272.0040	3082652.6750	J-28S	1.2	Manual	Т							

679329.4380	3082711.0960	J-29S	0.58	Manual T
679374.4420	3082791.3300	J-30S	0.54	Manual T
679410.1490	3082845.8460	J-31S	0.23	Manual T
679453.4760	3082914.1150	J-32S	1.1	Manual T
679495.8840	3082940.9730	J-33S	0.81	Manual T
679304.6530	3082548.6880	J-34S	0.8	Manual T
679342.7410	3082605.3190	J-35S	0.78	Manual T
679382.8900	3082667.5270	J-36S	1.7	Manual T
679433.9450	3082731.6820	J-37S	2.1	Manual T
679470.3570	3082776.7350	J-38S	2.2	Manual T
679497.3310	3082840.3960	J-39S	0.7	Manual T
679524.3310	3082886.8990	J-40S	0.62	Manual T
679560.6070	3082897.2580	J-41S	1.7	Manual T
679924.8150	3082872.3490	J-47S	1.3	Manual T
679994.9690	3082983.5100	J-48S	1.2	Manual T
680057.6580	3083072.0750	J-49S	0.69	Manual T
680077.3540	3083115.5330	J-50S	0.52	Manual T
679827.1150	3082729.7460	J-51S	0.63	Manual T
680141.8730	3083080.8800	J-52S	1.1	Manual T
680170.5600	3083064.6740	J-53S	2.4	Manual T
679129.3320	3082802.5620	Composite 1	0.22	Manual T
679124.7500	3082617.3010	Composite 3	1.6	Manual T
679107.0750	3082512.5600	Composite 4	0.25	Manual T
679240.6200	3082579.3320	Composite 2	0.44	Manual T

Area: Area 2									
X Coord	Y Coord	Label	Value	Туре	Historical				
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т				

Area: Area 3											
X Coord	Y Coord	Y Coord Label Value		Туре	Historical						
679356.9310	3083064.0350	J-62S	0.22	Manual	Т						
679396.8510	3083038.0640	J-64S	0.24	Manual	Т						
679386.3850	3083044.5490	J-63S	0.35	Manual	Т						
679341.9051	3083075.2504	J-65S	0.85	Random							

Area: Area 4									
X Coord	Y Coord	Label	Value	Туре	Historical				
679175.7550	3083152.6270	J-65S	0.85	Manual	Т				
679113.1200	3083190.3150	J-66S	0.18	Manual	Т				

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т
679270.2667	3083209.5643		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold.

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold.

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{-\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}$ a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of ß.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30

or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	N	lumbe	r of S	ample	s			
AL=2.50	nn E O	α=	=5	α=	10	α=15		
AL=2.50	1930	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	6188	1548	4897	1225	4111	1028	
LBGR=90	β=10	4897	1226	3757	940	3072	769	
	β=15	4111	1029	3073	769	2457	615	
	β=5	1548	388	1225	307	1028	258	
LBGR=80	β=10	1226	308	940	236	769	193	
	β=15	1029	259	769	193	615	155	
	β=5	689	174	545	137	458	115	
LBGR=70	β=10	546	138	419	106	342	86	
	β=15	458	116	343	87	274	69	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples							
Field collection costs		\$100.00	\$2,100.00							
Analytical costs	\$400.00	\$400.00	\$8,400.00							
Sum of Field & Analytical costs		\$500.00	\$10,500.00							
Fixed planning and validation costs			\$1,000.00							
Total cost			\$11,500.00							

Data Analysis

The following data points were entered by the user for analysis.

Rank 1 2 3	4 5 6	7 8 9 10
------------	-------	----------

0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.22
10	0.23	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28
20	0.28	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44
30	0.47	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74
40	0.78	0.8	0.81	0.85	0.85	0.94	0.94	1	1	1.1
50	1.1	1.2	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1
60	2.2	2.4	2.4							

SUMMARY STATISTICS								
n			63					
Min				0				
Max				2.4				
Range				2.4				
Mean			0.71349					
Median			0.52					
Variance			0.35464					
StdDev				0.59552				
Std Error				0.075028				
Skewness				1.3367				
Interquartile Range				0.75				
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.18	0.208	0.25	0.52	1	1.7	2.18	2.4

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	2.832	3.218	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1573	
Lilliefors 5% Critical Value	0.1125	

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic 0.1605					
Lilliefors 5% Critical Value	0.1116				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.8388				
95% Non-Parametric (Chebyshev) UCL	1.041				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.041) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (2.50958).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-23.939	1.6698	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
63	39	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	60
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1									
X Coord	Y Coord	Label	Value	Туре	Historical				
679149.4920	3082933.0980	J-13S	0.54	Manual	Т				
679279.6830	3083075.4290	J-14S	0.23	Manual	Т				
679261.0980	3083016.3510	J-15S	0.38	Manual	Т				
679222.6340	3082840.1720	J-16S	0.33	Manual	Т				
679293.5600	3082950.4980	J-17S	0.41	Manual	Т				
679360.5700	3083026.4980	J-18S	0.44	Manual	Т				
679343.5810	3082969.5980	J-19S	1.7	Manual	Т				
679382.8640	3083009.1130	J-20S	2.4	Manual	Т				
679335.0020	3082941.1720	J-21S	0.2	Manual	Т				
679252.7130	3082781.0290	J-22S	0.74	Manual	Т				
679297.0010	3082840.6970	J-23S	1.4	Manual	Т				
679394.8070	3082971.8300	J-24S	0.3	Manual	Т				
679146.6460	3082549.7640	J-25S	1	Manual	Т				
679224.5850	3082683.1400	J-26S	0.22	Manual	Т				
679169.0760	3082537.3510	J-27S	1	Manual	Т				
679272.0040	3082652.6750	J-28S	1.2	Manual	Т				

679329.4380 3082711.0960 J-29S 0.58 Manual T 679374.4420 3082791.3300 J-30S 0.54 Manual T 679410.1490 3082845.8460 J-31S 0.23 Manual T 679453.4760 3082914.1150 J-32S 1.1 Manual T 679495.8840 3082940.9730 J-33S 0.81 Manual T 679304.6530 3082548.6880 J-34S 0.8 Manual T 679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 30828872.3490 J-47S 1.3 Manual T 679924.8150 3082983						
679410.1490 3082845.8460 J-31S 0.23 Manual T 679453.4760 3082914.1150 J-32S 1.1 Manual T 679495.8840 3082940.9730 J-33S 0.81 Manual T 679304.6530 3082548.6880 J-34S 0.8 Manual T 679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680077.3540 3083115.53	679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679453.4760 3082914.1150 J-32S 1.1 Manual T 679495.8840 3082940.9730 J-33S 0.81 Manual T 679304.6530 3082548.6880 J-34S 0.8 Manual T 679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679524.8150 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680077.3540 3083115.533	679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679495.8840 3082940.9730 J-33S 0.81 Manual T 679304.6530 3082548.6880 J-34S 0.8 Manual T 679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680141.8730 3082802.56	679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679304.6530 3082548.6880 J-34S 0.8 Manual T 679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 680141.8730 3083080.88	679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679342.7410 3082605.3190 J-35S 0.78 Manual T 679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 30828872.3490 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679924.8150 3082872.3490 J-48S 1.2 Manual T 679924.8150 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 30828729.	679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679382.8900 3082667.5270 J-36S 1.7 Manual T 679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 680141.8730 3082729.7460 J-51S 0.63 Manual T 680170.5600 3083084.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 <td>679304.6530</td> <td>3082548.6880</td> <td>J-34S</td> <td>0.8</td> <td>Manual</td> <td>Т</td>	679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679433.9450 3082731.6820 J-37S 2.1 Manual T 679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680170.5600 3083080.8800 J-52S 1.1 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679470.3570 3082776.7350 J-38S 2.2 Manual T 679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679124.7500 3082617.3010 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679497.3310 3082840.3960 J-39S 0.7 Manual T 679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679524.3310 3082886.8990 J-40S 0.62 Manual T 679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679560.6070 3082897.2580 J-41S 1.7 Manual T 679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679924.8150 3082872.3490 J-47S 1.3 Manual T 679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679994.9690 3082983.5100 J-48S 1.2 Manual T 680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679560.6070	3082897.2580	J-41S	1.7	Manual	Т
680057.6580 3083072.0750 J-49S 0.69 Manual T 680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679924.8150	3082872.3490	J-47S	1.3	Manual	Т
680077.3540 3083115.5330 J-50S 0.52 Manual T 679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679994.9690	3082983.5100	J-48S	1.2	Manual	Т
679827.1150 3082729.7460 J-51S 0.63 Manual T 680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	680057.6580	3083072.0750	J-49S	0.69	Manual	Т
680141.8730 3083080.8800 J-52S 1.1 Manual T 680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	680077.3540	3083115.5330	J-50S	0.52	Manual	Т
680170.5600 3083064.6740 J-53S 2.4 Manual T 679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	679827.1150	3082729.7460	J-51S	0.63	Manual	Т
679129.3320 3082802.5620 Composite 1 0.22 Manual T 679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	680141.8730	3083080.8800	J-52S	1.1	Manual	Т
679124.7500 3082617.3010 Composite 3 1.6 Manual T 679107.0750 3082512.5600 Composite 4 0.25 Manual T	680170.5600	3083064.6740	J-53S	2.4	Manual	Т
679107.0750 3082512.5600 Composite 4 0.25 Manual T	679129.3320	3082802.5620	Composite 1	0.22	Manual	Т
	679124.7500	3082617.3010	Composite 3	1.6	Manual	Т
679240.6200 3082579.3320 Composite 2 0.44 Manual T	679107.0750	3082512.5600	Composite 4	0.25	Manual	Т
	679240.6200	3082579.3320	Composite 2	0.44	Manual	T

Area: Area 2						
X Coord Y Coord Label Value Type Historic						
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т	

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679356.9310	3083064.0350	J-62S	0.22	Manual	Т			
679396.8510	3083038.0640	J-64S	0.24	Manual	Т			
679386.3850	3083044.5490	J-63S	0.35	Manual	Т			
679353.3486	3083065.8470	J-65S	0.85	Random				

Area: Area 4							
X Coord	Y Coord	Label	Value	Туре	Historical		
679175.7550	3083152.6270	J-65S	0.85	Manual	Т		
679113.1200	3083190.3150	J-66S	0.18	Manual	Т		

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т
679126.2502	3083275.0474		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold.

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$.

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter						
Analyte	n	$S \Delta \alpha \beta Z_{1-\alpha}^{a} Z_{1-\beta}$					Z _{1-β} b	
	21	3	2	0.05	0.1	1.64485	1.28155	


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30

or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
41 000		α=	:5	α=10		α=15	
AL=0.3	9	s=6	=6 s=3 s		s=3	s=6	s=3
	β=5	256148	64038	202696	50675	170162	42541
LBGR=90	β=10	202696	50676	155492	38874	127174	31794
	β=15	170163	42542	127174	31795	101700	25426
	β=5	64038	16011	50675	12670	42541	10636
LBGR=80	β=10	50676	12670	38874	9720	31794	7949
	β=15	42542	10637	31795	7950	25426	6357
	β=5	28463	7117	22523	5632	18908	4728
LBGR=70	β=10	22523	5632	17278	4321	14131	3534
	β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

The following data points were entered by the user for analysis.

0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.23
10	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28	0.29
20	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44	0.47	0.52
30	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74	0.78	0.8
40	0.81	0.85	0.85	0.94	0.94	1	1	1.1	1.1	1.2
50	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1	2.2	2.4
60	2.4									

	SUMMARY STATISTICS							
			61					
	N	1in				0		
	N	lax				2.4		
	Ra	nge				2.4		
	M	ean			0	.7286	9	
	Me	0.54						
Variance				0.35904				
	Sto	0.5992						
	Std	0.076719						
	Skev	vness		1.2949				
Int	erquar	0.745						
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.18	0.204	0.255	0.54	1	1.7	2.19	2.4

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST						
k	k Test Statistic R _k 5% Critical Value C _k Significant						
1	2.781	3.2	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1619
Lilliefors 5% Critical Value	0.1153

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.1549				
Lilliefors 5% Critical Value	0.1134				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	0.8569			
95% Non-Parametric (Chebyshev) UCL	1.063			

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.063) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=61 data,

AL is the action level or threshold (0.39).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=60 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
4.4146	1.6706	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
25	37	Cannot Reject			

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	60					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area	a: Area	1		
X Coord	Y Coord	Label	Value	Туре	Historical
679149.4920	3082933.0980	J-13S	0.54	Manual	Т
679279.6830	3083075.4290	J-14S	0.23	Manual	Т
679261.0980	3083016.3510	J-15S	0.38	Manual	Т
679222.6340	3082840.1720	J-16S	0.33	Manual	Т
679293.5600	3082950.4980	J-17S	0.41	Manual	Т
679360.5700	3083026.4980	J-18S	0.44	Manual	Т
679343.5810	3082969.5980	J-19S	1.7	Manual	Т
679382.8640	3083009.1130	J-20S	2.4	Manual	Т
679335.0020	3082941.1720	J-21S	0.2	Manual	Т
679252.7130	3082781.0290	J-22S	0.74	Manual	Т
679297.0010	3082840.6970	J-23S	1.4	Manual	Т
679394.8070	3082971.8300	J-24S	0.3	Manual	Т
679146.6460	3082549.7640	J-25S	1	Manual	Т
679224.5850	3082683.1400	J-26S	0.22	Manual	Т
679169.0760	3082537.3510	J-27S	1	Manual	Т
679272.0040	3082652.6750	J-28S	1.2	Manual	Т

679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679560.6070	3082897.2580	J-41S	1.7	Manual	Т
679924.8150	3082872.3490	J-47S	1.3	Manual	Т
679994.9690	3082983.5100	J-48S	1.2	Manual	Т
680057.6580	3083072.0750	J-49S	0.69	Manual	Т
680077.3540	3083115.5330	J-50S	0.52	Manual	Т
679827.1150	3082729.7460	J-51S	0.63	Manual	Т
680141.8730	3083080.8800	J-52S	1.1	Manual	Т
680170.5600	3083064.6740	J-53S	2.4	Manual	Т
679129.3320	3082802.5620	Composite 1	0.22	Manual	Т
679124.7500	3082617.3010	Composite 3	1.6	Manual	Т
679107.0750	3082512.5600	Composite 4	0.25	Manual	Т
679240.6200	3082579.3320	Composite 2	0.44	Manual	Т
679856.3696	3083448.7662	Composite 5	0.94	Random	

Area: Area 2										
X Coord	Y Coord	Label	Value	Туре	Historical					
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т					
680457.3892	3082979.4959	J-62S	0.22	Random						

Area: Area 3											
X Coord	Y Coord	Label	Value	Туре	Historical						
679356.9310	3083064.0350	J-62S	0.22	Manual	Т						
679396.8510	3083038.0640	J-64S	0.24	Manual	Т						
679386.3850	3083044.5490	J-63S	0.35	Manual	Т						

Area: Area 4										
X Coord	Y Coord	Label	Value	Туре	Historical					
679175.7550	3083152.6270	J-65S	0.85	Manual	Т					
679113.1200	3083190.3150	J-66S	0.18	Manual	Т					

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta					ameter		
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

b This value is automatically calculated by VSP based upon the user defined value of β.

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	N	lumbe	r of S	ample	s		
AL=2.50	nn E O	α=	=5	α=	10	α=	15
AL=2.50	1930	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	6188	1548	4897	1225	4111	1028
LBGR=90	β=10	4897	1226	3757	940	3072	769
	β=15	4111	1029	3073	769	2457	615
	β=5	1548	388	1225	307	1028	258
LBGR=80	β=10	1226	308	940	236	769	193
	β=15	1029	259	769	193	615	155
	β=5	689	174	545	137	458	115
LBGR=70	β=10	546	138	419	106	342	86
	β=15	458	116	343	87	274	69

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST IN	COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples								
Field collection costs		\$100.00	\$2,100.00								
Analytical costs	\$400.00	\$400.00	\$8,400.00								
Sum of Field & Analytical costs		\$500.00	\$10,500.00								
Fixed planning and validation costs			\$1,000.00								
Total cost			\$11,500.00								

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.22

10	0.23	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28
20	0.28	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44
30	0.47	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74
40	0.78	8.0	0.81	0.85	0.85	0.94	0.94	1	1	1.1
50	1.1	1.2	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1
60	2.2	2.4	2.4							

		SUM	MARY	STA	TISTIC	CS		
		n		63				
	M	lin				0		
	М	ax				2.4		
	Ra	nge				2.4		
	М	ean		0	.7134	9		
	Me	dian	0.52					
	Vari	0.35464						
	Std	Dev		0.59552				
	Std	Error		0.075028				
	Skev	vness			•	1.3367	7	
Inte	erquar	tile Ra	nge	0.75				
			Perc	entile	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.18	0.208	0.25	0.52	1	1.7	2.18	2.4

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST					
	k	Test Statistic R _k	5% Critical Value C _k	Significant?		
ĺ	1	2.832	3.218	No		

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1573
Lilliefors 5% Critical Value	0.1125

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.1605				
Lilliefors 5% Critical Value	0.1116				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.8388				
95% Non-Parametric (Chebyshev) UCL	1.041				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.041) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (2.50958).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-23.939	1.6698	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
63	39	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	60					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1							
X Coord	Y Coord	Label	Value	Туре	Historical		
679149.4920	3082933.0980	J-13S	0.54	Manual	Т		
679279.6830	3083075.4290	J-14S	0.23	Manual	Т		
679261.0980	3083016.3510	J-15S	0.38	Manual	Т		
679222.6340	3082840.1720	J-16S	0.33	Manual	Т		
679293.5600	3082950.4980	J-17S	0.41	Manual	Т		
679360.5700	3083026.4980	J-18S	0.44	Manual	Т		
679343.5810	3082969.5980	J-19S	1.7	Manual	Т		
679382.8640	3083009.1130	J-20S	2.4	Manual	Т		
679335.0020	3082941.1720	J-21S	0.2	Manual	Т		
679252.7130	3082781.0290	J-22S	0.74	Manual	Т		
679297.0010	3082840.6970	J-23S	1.4	Manual	Т		
679394.8070	3082971.8300	J-24S	0.3	Manual	Т		
679146.6460	3082549.7640	J-25S	1	Manual	Т		
679224.5850	3082683.1400	J-26S	0.22	Manual	Т		
679169.0760	3082537.3510	J-27S	1	Manual	Т		
679272.0040	3082652.6750	J-28S	1.2	Manual	Т		

679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679560.6070	3082897.2580	J-41S	1.7	Manual	Т
679924.8150	3082872.3490	J-47S	1.3	Manual	Т
679994.9690	3082983.5100	J-48S	1.2	Manual	Т
680057.6580	3083072.0750	J-49S	0.69	Manual	Т
680077.3540	3083115.5330	J-50S	0.52	Manual	Т
679827.1150	3082729.7460	J-51S	0.63	Manual	Т
680141.8730	3083080.8800	J-52S	1.1	Manual	Т
680170.5600	3083064.6740	J-53S	2.4	Manual	Т
679129.3320	3082802.5620	Composite 1	0.22	Manual	Т
679124.7500	3082617.3010	Composite 3	1.6	Manual	Т
679107.0750	3082512.5600	Composite 4	0.25	Manual	Т
679240.6200	3082579.3320	Composite 2	0.44	Manual	Т
679856.3696	3083448.7662	Composite 5	0.94	Random	

Area: Area 2						
X Coord	Y Coord	Label	Value	Туре	Historical	
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т	
680457.3892	3082979.4959	J-62S	0.22	Random		

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679356.9310	3083064.0350	J-62S	0.22	Manual	Т	
679396.8510	3083038.0640	J-64S	0.24	Manual	Т	
679386.3850	3083044.5490	J-63S	0.35	Manual	Т	

Area: Area 4						
X Coord	Y Coord	Label	Value	Туре	Historical	
679175.7550	3083152.6270	J-65S	0.85	Manual	Т	
679113.1200	3083190.3150	J-66S	0.18	Manual	Т	

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta					Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

b This value is automatically calculated by VSP based upon the user defined value of β.

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=2.50	nn E O	α=	α=5		10	α=	15	
AL=2.50	1930	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	6188	1548	4897	1225	4111	1028	
LBGR=90	β=10	4897	1226	3757	940	3072	769	
	β=15	4111	1029	3073	769	2457	615	
	β=5	1548	388	1225	307	1028	258	
LBGR=80	β=10	1226	308	940	236	769	193	
	β=15	1029	259	769	193	615	155	
LBGR=70	β=5	689	174	545	137	458	115	
	β=10	546	138	419	106	342	86	
	β=15	458	116	343	87	274	69	

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.22

10	0.23	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28
20	0.28	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44
30	0.47	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74
40	0.78	8.0	0.81	0.85	0.85	0.94	0.94	1	1	1.1
50	1.1	1.2	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1
60	2.2	2.4	2.4							

	SUMMARY STATISTICS								
		63							
	M	lin				0			
	М	ax				2.4			
	Ra	nge				2.4			
	М	ean			0	.7134	9		
Median						0.52			
	Vari	ance		0.35464					
	Std	Dev		0.59552					
	Std	Error		0.075028					
	Skev	vness		1.3367					
Inte	erquar	tile Ra	0.75						
		entile	es						
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	0.18	0.208	0.25	0.52	1	1.7	2.18	2.4	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST							
	k	Test Statistic R _k	5% Critical Value C _k	Significant?				
ĺ	1	2.832	3.218	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1573
Lilliefors 5% Critical Value	0.1125

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Lilliefors Test Statistic	0.1605					
Lilliefors 5% Critical Value	0.1116					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.8388
95% Non-Parametric (Chebyshev) UCL	1.041

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.041) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (2.50958).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Null Hypothesis					
-23.939	1.6698	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
63	39	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold				
Type of Sampling Design	Parametric				
Sample Placement (Location) in the Field	Simple random sampling				
Working (Null) Hypothesis	The mean value at the site exceeds the threshold				
Formula for calculating number of sampling locations	Student's t-test				
Calculated total number of samples	21				
Number of samples on map ^a	60				
Number of selected sample areas b	5				
Specified sampling area ^c	941426.62 m ²				
Total cost of sampling d	\$11,500.00				

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1						
X Coord	Y Coord	Label	Value	Туре	Historical	
679149.4920	3082933.0980	J-13S	0.54	Manual	Т	
679279.6830	3083075.4290	J-14S	0.23	Manual	Т	
679261.0980	3083016.3510	J-15S	0.38	Manual	Т	
679222.6340	3082840.1720	J-16S	0.33	Manual	Т	
679293.5600	3082950.4980	J-17S	0.41	Manual	Т	
679360.5700	3083026.4980	J-18S	0.44	Manual	Т	
679343.5810	3082969.5980	J-19S	1.7	Manual	Т	
679382.8640	3083009.1130	J-20S	2.4	Manual	Т	
679335.0020	3082941.1720	J-21S	0.2	Manual	Т	
679252.7130	3082781.0290	J-22S	0.74	Manual	Т	
679297.0010	3082840.6970	J-23S	1.4	Manual	Т	
679394.8070	3082971.8300	J-24S	0.3	Manual	Т	
679146.6460	3082549.7640	J-25S	1	Manual	Т	
679224.5850	3082683.1400	J-26S	0.22	Manual	Т	
679169.0760	3082537.3510	J-27S	1	Manual	Т	
679272.0040	3082652.6750	J-28S	1.2	Manual	Т	

679329.4380 3	8082711.0960	J-29S	0.58	Manual T
679374.4420 3	8082791.3300	J-30S	0.54	Manual T
679410.1490 3	082845.8460	J-31S	0.23	Manual T
679453.4760 3	8082914.1150	J-32S	1.1	Manual T
679495.8840 3	3082940.9730	J-33S	0.81	Manual T
679304.6530 3	082548.6880	J-34S	0.8	Manual T
679342.7410 3	082605.3190	J-35S	0.78	Manual T
679382.8900 3	3082667.5270	J-36S	1.7	Manual T
679433.9450 3	082731.6820	J-37S	2.1	Manual T
679470.3570 3	082776.7350	J-38S	2.2	Manual T
679497.3310 3	082840.3960	J-39S	0.7	Manual T
679524.3310 3	082886.8990	J-40S	0.62	Manual T
679560.6070 3	082897.2580	J-41S	1.7	Manual T
679924.8150 3	082872.3490	J-47S	1.3	Manual T
679994.9690 3	082983.5100	J-48S	1.2	Manual T
680057.6580 3	3083072.0750	J-49S	0.69	Manual T
680077.3540 3	083115.5330	J-50S	0.52	Manual T
679827.1150 3	082729.7460	J-51S	0.63	Manual T
680141.8730 3	083080.8800	J-52S	1.1	Manual T
680170.5600 3	083064.6740	J-53S	2.4	Manual T
679129.3320 3	082802.5620	Composite 1	0.22	Manual T
679124.7500 3	3082617.3010	Composite 3	1.6	Manual T
679107.0750 3	082512.5600	Composite 4	0.25	Manual T
679240.6200 3	3082579.3320	Composite 2	0.44	Manual T

Area: Area 2					
X Coord Y Coord Label Value Type Historic					Historical
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т

Area: Area 3					
X Coord	Y Coord	Label	Value	Туре	Historical
679356.9310	3083064.0350	J-62S	0.22	Manual	Т
679396.8510	3083038.0640	J-64S	0.24	Manual	Т
679386.3850	3083044.5490	J-63S	0.35	Manual	Т
679384.2850	3083049.8773	J-65S	0.85	Random	

Area: Area 4					
X Coord	Y Coord	Label	Value	Туре	Historical
679175.7550	3083152.6270	J-65S	0.85	Manual	Т
679113.1200	3083190.3150	J-66S	0.18	Manual	Т
679161.8021	3083152.5891	J-01S	0.28	Random	

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.28	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.2	Manual	Т
679171.2970	3083289.7960	J-04S	0.23	Manual	Т
679225.8560	3083359.9740	J-05S	0.16	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.27	Manual	Т
679280.5440	3083305.6810	J-10S	0.27	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.18	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta					Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}^{a}$	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AI -24	2	α=5		α=10		α=15	
AL=24.2		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	68	18	54	14	45	12
LBGR=90	β=10	54	15	42	11	34	9
	β=15	46	13	34	10	27	8
	β=5	18	6	14	5	12	4
LBGR=80	β=10	15	5	11	4	9	3
	β=15	13	5	10	3	8	3
LBGR=70	β=5	9	4	7	3	6	2
	β=10	8	3	6	2	5	2
	β=15	7	3	5	2	4	2

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.16	0.18	0.18	0.2	0.2	0.22	0.22	0.22	0.23

10	0.23	0.23	0.23	0.24	0.25	0.26	0.27	0.27	0.28	0.28
20	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44	0.47
30	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74	0.78
40	8.0	0.81	0.85	0.85	0.94	0.94	1	1	1.1	1.1
50	1.2	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1	2.2
60	2.4	2.4								

	cs									
		n		62						
	ľ	Min				0				
	N	<i>l</i> lax				2.4				
	Ra	ange				2.4				
	M	lean			(0.7214	1 5			
	Median					0.53				
	Var	iance		0.3564						
	Sto	dDev		0.59699						
	Std	Error		0.075818						
	Ske	wness		1.3176						
Int	erqua	0.7425								
			Perc	centiles						
1%	5%	10%	25%	50%	75%	90%	95%	99%		
0	0.18	0.206	0.2575	0.53	1	1.7	2.185	2.4		

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST						
	k	Test Statistic R _k	5% Critical Value C _k	Significant?			
ĺ	1	2.789	3.206	No			

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)

Lilliefors Test Statistic	0.1517
Lilliefors 5% Critical Value	0.1144

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.1574				
Lilliefors 5% Critical Value	0.1125				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.8481
95% Non-Parametric (Chebyshev) UCL	1.052

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (1.052) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=62 data,

AL is the action level or threshold (24.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=61 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-309.67	1.6702	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
62	38	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	60
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area	a: Area	1		
X Coord	Y Coord	Label	Value	Туре	Historical
679149.4920	3082933.0980	J-13S	0.54	Manual	Т
679279.6830	3083075.4290	J-14S	0.115	Manual	Т
679261.0980	3083016.3510	J-15S	0.38	Manual	Т
679222.6340	3082840.1720	J-16S	0.33	Manual	Т
679293.5600	3082950.4980	J-17S	0.41	Manual	Т
679360.5700	3083026.4980	J-18S	0.44	Manual	Т
679343.5810	3082969.5980	J-19S	1.7	Manual	Т
679382.8640	3083009.1130	J-20S	0.12	Manual	Т
679335.0020	3082941.1720	J-21S	0.1	Manual	Т
679252.7130	3082781.0290	J-22S	0.74	Manual	Т
679297.0010	3082840.6970	J-23S	1.4	Manual	Т
679394.8070	3082971.8300	J-24S	0.3	Manual	Т
679146.6460	3082549.7640	J-25S	1	Manual	Т
679224.5850	3082683.1400	J-26S	0.11	Manual	Т
679169.0760	3082537.3510	J-27S	1	Manual	Т
679272.0040	3082652.6750	J-28S	1.2	Manual	Т

679329.4380	3082711.0960	J-29S	0.58	Manual	Т
679374.4420	3082791.3300	J-30S	0.54	Manual	Т
679410.1490	3082845.8460	J-31S	0.23	Manual	Т
679453.4760	3082914.1150	J-32S	1.1	Manual	Т
679495.8840	3082940.9730	J-33S	0.81	Manual	Т
679304.6530	3082548.6880	J-34S	0.8	Manual	Т
679342.7410	3082605.3190	J-35S	0.78	Manual	Т
679382.8900	3082667.5270	J-36S	1.7	Manual	Т
679433.9450	3082731.6820	J-37S	2.1	Manual	Т
679470.3570	3082776.7350	J-38S	2.2	Manual	Т
679497.3310	3082840.3960	J-39S	0.7	Manual	Т
679524.3310	3082886.8990	J-40S	0.62	Manual	Т
679560.6070	3082897.2580	J-41S	1.7	Manual	Т
679924.8150	3082872.3490	J-47S	1.3	Manual	Т
679994.9690	3082983.5100	J-48S	1.2	Manual	Т
680057.6580	3083072.0750	J-49S	0.69	Manual	Т
680077.3540	3083115.5330	J-50S	0.52	Manual	Т
679827.1150	3082729.7460	J-51S	0.63	Manual	Т
680141.8730	3083080.8800	J-52S	1.1	Manual	Т
680170.5600	3083064.6740	J-53S	2.4	Manual	Т
679129.3320	3082802.5620	Composite 1	0.11	Manual	Т
679240.6200	3082579.3320	Composite 2	1.6	Manual	Т
679124.7500	3082617.3010	Composite 3	0.125	Manual	Т
679107.0750	3082512.5600	Composite 4	0.44	Manual	Т
679094.8663	3082845.4445	Composite 5	0.94	Random	

Area: Area 2										
X Coord	Y Coord	Label	Value	Туре	Historical					
680320.6560	3082842.6400	Composite 5	0.94	Manual	Т					
680563.9121	3083116.7817	J-62S	0.11	Random						

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679356.9310	3083064.0350	J-62S	0.11	Manual	Т					
679386.3850	3083044.5490	J-63S	0.35	Manual	Т					
679396.8510	3083038.0640	J-64S	0.12	Manual	Т					

Area: Area 4									
X Coord	Y Coord	Label	Value	Туре	Historical				
679175.7550	3083152.6270	J-65S	0.85	Manual	Т				
679113.1200	3083190.3150	J-66S	0.09	Manual	Т				

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.14	Manual	Т
679104.2450	3083223.2620	J-02S	0.34	Manual	Т
679155.0740	3083294.6960	J-03S	0.1	Manual	Т
679171.2970	3083289.7960	J-04S	0.115	Manual	Т
679225.8560	3083359.9740	J-05S	0.08	Manual	Т
679164.8060	3083214.7100	J-06S	0.23	Manual	Т
679242.7260	3083326.5280	J-07S	0.47	Manual	Т
679181.2750	3083178.2880	J-08S	0.29	Manual	Т
679213.7730	3083224.9730	J-09S	0.105	Manual	Т
679280.5440	3083305.6810	J-10S	0.105	Manual	Т
679268.7700	3083200.3260	J-11S	0.26	Manual	Т
679301.1600	3083254.0340	J-12S	0.09	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte		Parameter						
	n	S	Δ	α	β	$Z_{1-\alpha}^{a}$	Z_{1-β} b	
	21	3	2	0.05	0.1	1.64485	1.28155	

^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples									
AL=0.3	20	α=	5	α=	10	α=′	15			
AL=0.39		s=6	s=3	s=3 s=6 s=3		s=6	s=3			
	β=5	256148	64038	202696	50675	170162	42541			
LBGR=90	β=10	202696	50676	155492	38874	127174	31794			
	β=15	170163	42542	127174	31795	101700	25426			
	β=5	64038	16011	50675	12670	42541	10636			
LBGR=80	β=10	50676	12670	38874	9720	31794	7949			
	β=15	42542	10637	31795	7950	25426	6357			
	β=5	28463	7117	22523	5632	18908	4728			
LBGR=70	β=10	22523	5632	17278	4321	14131	3534			
	β=15	18909	4729	14132	3534	11301	2826			

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST IN	COST INFORMATION											
Cost Details	Per Analysis	Per Sample	21 Samples									
Field collection costs		\$100.00	\$2,100.00									
Analytical costs	\$400.00	\$400.00	\$8,400.00									
Sum of Field & Analytical costs		\$500.00	\$10,500.00									
Fixed planning and validation costs			\$1,000.00									
Total cost			\$11,500.00									

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.08	0.09	0.09	0.1	0.1	0.105	0.105	0.11	0.11	0.11

10	0.11	0.115	0.115	0.12	0.12	0.125	0.14	0.23	0.23	0.26
20	0.29	0.3	0.33	0.34	0.35	0.38	0.41	0.44	0.44	0.47
30	0.52	0.54	0.54	0.58	0.62	0.63	0.69	0.7	0.74	0.78
40	8.0	0.81	0.85	0.94	0.94	1	1	1.1	1.1	1.2
50	1.2	1.3	1.4	1.6	1.7	1.7	1.7	2.1	2.2	2.4

	SUMMARY STATISTICS								
	n				60				
	M	lin			(3.08			
	М	ах				2.4			
	Ra	nge			2	2.32			
Mean					0.6	66158	1		
	Median			0.495					
	Vari	ance		0.3496					
	Std	Dev		0.59127					
	Std	Error		0.076332					
	Skew	vness		1.1838					
In	Interquartile Range			0.86375					
	Perce								
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.08	0.0905	0.105	0.1213	0.495	0.985	1.69	2.08	2.4	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	2.909	3.186	No				

None of the test statistics exceeded the corresponding critical values, therefore none of the 1 tests are significant and we conclude that at the 5% significance level there are no outliers in the data.

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.1578

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.1627				
Lilliefors 5% Critical Value	0.1144				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	0.7891					
95% Non-Parametric (Chebyshev) UCL	0.9943					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.9943) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=60 data,

AL is the action level or threshold (0.39).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=59 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic Critical Value $t_{0.95}$ Null Hypothesis						
3.5579	1.6711	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+) 95% Critical Value Null Hypothesis						
26	37	Cannot Reject				

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	60					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1							
X Coord	Y Coord	Label	Value	Туре	Historical		
679149.4920	3082933.0980	J-13S	0.077	Manual	Т		
679279.6830	3083075.4290	J-14S	0.077	Manual	Т		
679261.0980	3083016.3510	J-15S	0.07	Manual	Т		
679222.6340	3082840.1720	J-16S	0.072	Manual	Т		
679293.5600	3082950.4980	J-17S	0.079	Manual	Т		
679360.5700	3083026.4980	J-18S	0.074	Manual	Т		
679343.5810	3082969.5980	J-19S	0.077	Manual	Т		
679382.8640	3083009.1130	J-20S	0.83	Manual	Т		
679335.0020	3082941.1720	J-21S	0.073	Manual	Т		
679252.7130	3082781.0290	J-22S	0.072	Manual	Т		
679297.0010	3082840.6970	J-23S	0.071	Manual	Т		
679394.8070	3082971.8300	J-24S	0.073	Manual	Т		
679146.6460	3082549.7640	J-25S	0.064	Manual	Т		
679224.5850	3082683.1400	J-26S	0.072	Manual	Т		
679169.0760	3082537.3510	J-27S	0.072	Manual	Т		
679272.0040	3082652.6750	J-28S	0.073	Manual	Т		

679329.4380	3082711.0960	J-29S	0.071	Manual	Т
679374.4420	3082791.3300	J-30S	0.074	Manual	Т
679410.1490	3082845.8460	J-31S	0.079	Manual	Т
679453.4760	3082914.1150	J-32S	0.076	Manual	Т
679495.8840	3082940.9730	J-33S	0.073	Manual	Т
679304.6530	3082548.6880	J-34S	0.073	Manual	Т
679342.7410	3082605.3190	J-35S	0.076	Manual	Т
679382.8900	3082667.5270	J-36S	0.074	Manual	Т
679433.9450	3082731.6820	J-37S	0.071	Manual	Т
679470.3570	3082776.7350	J-38S	0.078	Manual	Т
679497.3310	3082840.3960	J-39S	0.074	Manual	Т
679524.3310	3082886.8990	J-40S	0.074	Manual	Т
679560.6070	3082897.2580	J-41S	0.072	Manual	Т
679924.8150	3082872.3490	J-47S	0.076	Manual	Т
679994.9690	3082983.5100	J-48S	0.076	Manual	Т
680057.6580	3083072.0750	J-49S	0.079	Manual	Т
680077.3540	3083115.5330	J-50S	0.076	Manual	Т
679827.1150	3082729.7460	J-51S	0.074	Manual	Т
680141.8730	3083080.8800	J-52S	0.076	Manual	Т
680170.5600	3083064.6740	J-53S	0.075	Manual	Т
679129.3320	3082802.5620	Composite 1	0.074	Manual	Т
679124.7500	3082617.3010	Composite 3	0.076	Manual	Т
679107.0750	3082512.5600	Composite 4	0.074	Manual	Т
679240.6200	3082579.3320	Composite 2	0.075	Manual	Т

Area: Area 2							
X Coord Y Coord Label Value Type Historic							
680320.6560	3082842.6400	Composite 5	0.073	Manual	Т		

Area: Area 3								
X Coord	Y Coord	Label	Value	Туре	Historical			
679356.9310	3083064.0350	J-62S	0.073	Manual	Т			
679396.8510	3083038.0640	J-64S	0.074	Manual	Т			
679386.3850	3083044.5490	J-63S	0.071	Manual	Т			

	Area: Area 4											
X Coord	Y Coord	Label	Value	Туре	Historical							
679175.7550	3083152.6270	J-65S	0.066	Manual	Т							
679113.1200	3083190.3150	J-66S	0.067	Manual	Т							
679171.2061	3083131.7267	J-01S	0.085	Random								

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.085	Manual	Т
679104.2450	3083223.2620	J-02S	0.07	Manual	Т
679155.0740	3083294.6960	J-03S	0.082	Manual	Т
679171.2970	3083289.7960	J-04S	0.33	Manual	Т
679225.8560	3083359.9740	J-05S	0.075	Manual	Т
679164.8060	3083214.7100	J-06S	0.07	Manual	Т
679242.7260	3083326.5280	J-07S	0.07	Manual	Т
679181.2750	3083178.2880	J-08S	0.071	Manual	Т
679213.7730	3083224.9730	J-09S	0.072	Manual	Т
679280.5440	3083305.6810	J-10S	0.073	Manual	Т
679268.7700	3083200.3260	J-11S	0.083	Manual	Т
679301.1600	3083254.0340	J-12S	0.072	Manual	Т
679273.1230	3083282.5024		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold.

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30

b This value is automatically calculated by VSP based upon the user defined value of β.

or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples											
AL=0.1	ΛO	α=	5	α=	10	α=15						
AL=0.1	UO	s=6 s=3		s=6	s=3	s=6	s=3					
	β=5	3340179	835046	2643164	660792	2218921	554731					
LBGR=90	β=10	2643165	660793	2027624	506907	1658351	414589					
	β=15	2218922	554732	1658351	414589	1326167	331542					
	β=5	835046	208763	660792	165199	554731	138684					
LBGR=80	β=10	660793	165200	506907	126728	414589	103648					
	β=15	554732	138684	414589	103648	331542	82886					
	β=5	371133	92785	293686	73423	246548	61638					
LBGR=70	β=10	293687	73423	225293	56324	184262	46066					
	β=15	246548	61639	184262	46067	147353	36839					

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples							
Field collection costs		\$100.00	\$2,100.00							
Analytical costs	\$400.00	\$400.00	\$8,400.00							
Sum of Field & Analytical costs		\$500.00	\$10,500.00							
Fixed planning and validation costs			\$1,000.00							
Total cost			\$11,500.00							

Data Analysis

The following data points were entered by the user for analysis.

Rank 1 2 3 4 5 6 7 8	10	9			2	2		1	Rank	
----------------------	----	---	--	--	---	---	--	---	------	--

0	0	0.064	0.066	0.067	0.07	0.07	0.07	0.07	0.07	0.071
10	0.071	0.071	0.071	0.071	0.072	0.072	0.072	0.072	0.072	0.072
20	0.072	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.074
30	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.075	0.075
40	0.075	0.076	0.076	0.076	0.076	0.076	0.076	0.076	0.077	0.077
50	0.077	0.078	0.079	0.079	0.079	0.082	0.083	0.085	0.085	0.33
60	0.83									

	SUMMARY STATISTICS										
	n					61					
	Mi	n				0					
	Ма	ıx				0.83					
	Ran	ge				0.83					
	Ме	an			(0.08941					
	Med	ian				0.074					
	Varia	nce		0.010483							
	StdI	Dev		0.10239							
	Std E	rror		0.013109							
	Skew	ness		6.7295							
In	terquart	ile Raı	nge	0.004							
			Pe	rcentil	es						
1%	5%	10%	25%	50%	75%	90%	95%	99%			
0	0.0661	0.07	0.072	0.074	0.076	0.0814	0.085	0.83			

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST									
k	k Test Statistic R _k 5% Critical Value C _k Significant?									
1	7.205	3.2	Yes							

The test statistic 7.205 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	0.83

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is

recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level

NORMAL DISTRIBUTION TEST (excluding outliers									
Lilliefors Test Statistic	0.4078								
Lilliefors 5% Critical Value	0.1153								

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST								
Lilliefors Test Statistic	0.4844							
Lilliefors 5% Critical Value	0.1134							

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	0.1113				
95% Non-Parametric (Chebyshev) UCL	0.1466				

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1466) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=61 data,

AL is the action level or threshold (0.108).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=60 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
-1.4181	1.6706	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
59	37	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	21						
Number of samples on map ^a	60						
Number of selected sample areas b	5						
Specified sampling area ^c	941426.62 m ²						
Total cost of sampling d	\$11,500.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1										
X Coord	Y Coord	Label	Value	Туре	Historical					
679149.4920	3082933.0980	J-13S	0.077	Manual	Т					
679279.6830	3083075.4290	J-14S	0.077	Manual	Т					
679261.0980	3083016.3510	J-15S	0.07	Manual	Т					
679222.6340	3082840.1720	J-16S	0.072	Manual	Т					
679293.5600	3082950.4980	J-17S	0.079	Manual	Т					
679360.5700	3083026.4980	J-18S	0.074	Manual	Т					
679343.5810	3082969.5980	J-19S	0.077	Manual	Т					
679382.8640	3083009.1130	J-20S	0.83	Manual	Т					
679335.0020	3082941.1720	J-21S	0.073	Manual	Т					
679252.7130	3082781.0290	J-22S	0.072	Manual	Т					
679297.0010	3082840.6970	J-23S	0.071	Manual	Т					
679394.8070	3082971.8300	J-24S	0.073	Manual	Т					
679146.6460	3082549.7640	J-25S	0.064	Manual	Т					
679224.5850	3082683.1400	J-26S	0.072	Manual	Т					
679169.0760	3082537.3510	J-27S	0.072	Manual	Т					
679272.0040	3082652.6750	J-28S	0.073	Manual	Т					

679374.4420 3082791.3300 J-30S 0.074 Manual T 679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679470.3570 3082776.7350 J-38S 0.074 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679560.6070 3082897.2580 J-40S 0.074 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 680057.6580 3083072.0750 J-48S 0.076 Manual T 680077.3540						
679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.076 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083080.8800 J-52S 0.076 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679329.4380	3082711.0960	J-29S	0.071	Manual	Т
679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680077.3540	679374.4420	3082791.3300	J-30S	0.074	Manual	Т
679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680141.8730	679410.1490	3082845.8460	J-31S	0.079	Manual	Т
679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680141.8730 3083082.820.5620 J-51S 0.076 Manual T 680170.5600 <td>679453.4760</td> <td>3082914.1150</td> <td>J-32S</td> <td>0.076</td> <td>Manual</td> <td>Т</td>	679453.4760	3082914.1150	J-32S	0.076	Manual	Т
679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600	679495.8840	3082940.9730	J-33S	0.073	Manual	Т
679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3083080.8800 J-51S 0.074 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320	679304.6530	3082548.6880	J-34S	0.073	Manual	Т
679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320	679342.7410	3082605.3190	J-35S	0.076	Manual	Т
679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679382.8900	3082667.5270	J-36S	0.074	Manual	Т
679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679433.9450	3082731.6820	J-37S	0.071	Manual	Т
679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679470.3570	3082776.7350	J-38S	0.078	Manual	Т
679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679497.3310	3082840.3960	J-39S	0.074	Manual	Т
679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679524.3310	3082886.8990	J-40S	0.074	Manual	Т
679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679560.6070	3082897.2580	J-41S	0.072	Manual	Т
680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679924.8150	3082872.3490	J-47S	0.076	Manual	Т
680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679994.9690	3082983.5100	J-48S	0.076	Manual	Т
679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	680057.6580	3083072.0750	J-49S	0.079	Manual	Т
680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	680077.3540	3083115.5330	J-50S	0.076	Manual	Т
680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T	679827.1150	3082729.7460	J-51S	0.074	Manual	Т
679129.3320 3082802.5620 Composite 1 0.074 Manual T	680141.8730	3083080.8800	J-52S	0.076	Manual	Т
	680170.5600	3083064.6740	J-53S	0.075	Manual	Т
679124 7500 3082617 3010 Composite 3 0 076 Manual T	679129.3320	3082802.5620	Composite 1	0.074	Manual	Т
073124.7300 3002017.3010 Composite 3 0.070 Warida	679124.7500	3082617.3010	Composite 3	0.076	Manual	Т
679107.0750 3082512.5600 Composite 4 0.074 Manual T	679107.0750	3082512.5600	Composite 4	0.074	Manual	Т
679240.6200 3082579.3320 Composite 2 0.075 Manual T	679240.6200	3082579.3320	Composite 2	0.075	Manual	Т
680060.2624 3083119.4017 Composite 5 0.073 Random	680060.2624	3083119.4017	Composite 5	0.073	Random	

Area: Area 2								
X Coord	Y Coord	Label	Value	Туре	Historical			
680320.6560	3082842.6400	Composite 5	0.073	Manual	Т			

Area: Area 3									
X Coord	Y Coord	Label	Value	Туре	Historical				
679356.9310	3083064.0350	J-62S	0.073	Manual	Т				
679396.8510	3083038.0640	J-64S	0.074	Manual	Т				
679386.3850	3083044.5490	J-63S	0.071	Manual	Т				

Area: Area 4									
X Coord	Y Coord	Label	Value	Туре	Historical				
679175.7550	3083152.6270	J-65S	0.066	Manual	Т				
679113.1200	3083190.3150	J-66S	0.067	Manual	Т				
679015.7816	3083233.7284	J-01S	0.085	Random					

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.085	Manual	Т
679104.2450	3083223.2620	J-02S	0.07	Manual	Т
679155.0740	3083294.6960	J-03S	0.082	Manual	Т
679171.2970	3083289.7960	J-04S	0.33	Manual	Т
679225.8560	3083359.9740	J-05S	0.075	Manual	Т
679164.8060	3083214.7100	J-06S	0.07	Manual	Т
679242.7260	3083326.5280	J-07S	0.07	Manual	Т
679181.2750	3083178.2880	J-08S	0.071	Manual	Т
679213.7730	3083224.9730	J-09S	0.072	Manual	Т
679280.5440	3083305.6810	J-10S	0.073	Manual	Т
679268.7700	3083200.3260	J-11S	0.083	Manual	Т
679301.1600	3083254.0340	J-12S	0.072	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_		Parameter				
Analyte n	n	S	Δ	α	β	$Z_{1-\alpha}^{a}$	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples										
AL=0.261		α=	=5	α=	10	α=15				
		s=6	s=3	s=6 s=3		s=6	s=3			
	β=5	571923	142982	452576	113145	379935	94985			
LBGR=90	β=10	452577	113146	347180	86796	283952	70989			
	β=15	379936	94985	283952	70989	227073	56769			
	β=5	142982	35747	113145	28287	94985	23747			
LBGR=80	β=10	113146	28288	86796	21700	70989	17748			
	β=15	94985	23748	70989	17748	56769	14193			
	β=5	63549	15889	50287	12573	42216	10555			
LBGR=70	β=10	50288	12573	38577	9645	31551	7889			
	β=15	42217	10556	31551	7889	25231	6309			

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.064	0.066	0.066	0.067	0.07	0.07	0.07	0.07	0.07

	10	0.071	0.071	0.071	0.071	0.071	0.072	0.072	0.072	0.072	0.072
	20	0.072	0.072	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073
,	30	0.073	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074
-	40	0.075	0.075	0.075	0.076	0.076	0.076	0.076	0.076	0.076	0.076
	50	0.077	0.077	0.077	0.078	0.079	0.079	0.079	0.082	0.083	0.085
	60	0.085	0.33	0.83							

	SUMMARY STATISTICS							
n				63				
	M	in				0		
	M	ах				0.83		
	Rai	nge				0.83		
	Me	an			0	0.088778		
Median				0.074				
Variance				0.010157				
StdDev				0.10078				
	Std I	Error		0.012698				
Skewness					6.8396			
Interquartile Range				0.004				
P				rercentiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.066	0.07	0.072	0.074	0.076	0.0808	0.085	0.83

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	7.294	3.212	Yes		

The test statistic 7.294 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	0.83	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the

suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers		
Lilliefors Test Statistic	0.3936	
Lilliefors 5% Critical Value	0.1134	

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4832			
Lilliefors 5% Critical Value	0.1116			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.11
95% Non-Parametric (Chebyshev) UCL	0.1441

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1441) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (0.261).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-13.563	1.6698	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
61	39	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	60
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area	a: Area	1		
X Coord	Y Coord	Label	Value	Туре	Historical
679149.4920	3082933.0980	J-13S	0.077	Manual	Т
679279.6830	3083075.4290	J-14S	0.077	Manual	Т
679261.0980	3083016.3510	J-15S	0.07	Manual	Т
679222.6340	3082840.1720	J-16S	0.072	Manual	Т
679293.5600	3082950.4980	J-17S	0.079	Manual	Т
679360.5700	3083026.4980	J-18S	0.074	Manual	Т
679343.5810	3082969.5980	J-19S	0.077	Manual	Т
679382.8640	3083009.1130	J-20S	0.83	Manual	Т
679335.0020	3082941.1720	J-21S	0.073	Manual	Т
679252.7130	3082781.0290	J-22S	0.072	Manual	Т
679297.0010	3082840.6970	J-23S	0.071	Manual	Т
679394.8070	3082971.8300	J-24S	0.073	Manual	Т
679146.6460	3082549.7640	J-25S	0.064	Manual	Т
679224.5850	3082683.1400	J-26S	0.072	Manual	Т
679169.0760	3082537.3510	J-27S	0.072	Manual	Т
679272.0040	3082652.6750	J-28S	0.073	Manual	Т

679329.4380	3082711.0960	J-29S	0.071	Manual	Т
679374.4420	3082791.3300	J-30S	0.074	Manual	Т
679410.1490	3082845.8460	J-31S	0.079	Manual	Т
679453.4760	3082914.1150	J-32S	0.076	Manual	Т
679495.8840	3082940.9730	J-33S	0.073	Manual	Т
679304.6530	3082548.6880	J-34S	0.073	Manual	Т
679342.7410	3082605.3190	J-35S	0.076	Manual	Т
679382.8900	3082667.5270	J-36S	0.074	Manual	Т
679433.9450	3082731.6820	J-37S	0.071	Manual	Т
679470.3570	3082776.7350	J-38S	0.078	Manual	Т
679497.3310	3082840.3960	J-39S	0.074	Manual	Т
679524.3310	3082886.8990	J-40S	0.074	Manual	Т
679560.6070	3082897.2580	J-41S	0.072	Manual	Т
679924.8150	3082872.3490	J-47S	0.076	Manual	Т
679994.9690	3082983.5100	J-48S	0.076	Manual	Т
680057.6580	3083072.0750	J-49S	0.079	Manual	Т
680077.3540	3083115.5330	J-50S	0.076	Manual	Т
679827.1150	3082729.7460	J-51S	0.074	Manual	Т
680141.8730	3083080.8800	J-52S	0.076	Manual	Т
680170.5600	3083064.6740	J-53S	0.075	Manual	Т
679129.3320	3082802.5620	Composite 1	0.074	Manual	Т
679124.7500	3082617.3010	Composite 3	0.076	Manual	Т
679107.0750	3082512.5600	Composite 4	0.074	Manual	Т
679240.6200	3082579.3320	Composite 2	0.075	Manual	Т

Area: Area 2									
X Coord	Y Coord	Label	Value	Туре	Historical				
680320.6560	3082842.6400	Composite 5	0.073	Manual	Т				
680548.6718	3083251.2433	J-62S	0.073	Random					

Area: Area 3										
X Coord	Y Coord	Label	Value	Туре	Historical					
679356.9310	3083064.0350	J-62S	0.073	Manual	Т					
679396.8510	3083038.0640	J-64S	0.074	Manual	Т					
679386.3850	3083044.5490	J-63S	0.071	Manual	Т					

Area: Area 4									
X Coord	Y Coord	Label	Value	Туре	Historical				
679175.7550	3083152.6270	J-65S	0.066	Manual	Т				
679113.1200	3083190.3150	J-66S	0.067	Manual	Т				
679198.3689	3083138.7797	J-01S	0.085	Random					

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.085	Manual	Т
679104.2450	3083223.2620	J-02S	0.07	Manual	Т
679155.0740	3083294.6960	J-03S	0.082	Manual	Т
679171.2970	3083289.7960	J-04S	0.33	Manual	Т
679225.8560	3083359.9740	J-05S	0.075	Manual	Т
679164.8060	3083214.7100	J-06S	0.07	Manual	Т
679242.7260	3083326.5280	J-07S	0.07	Manual	Т
679181.2750	3083178.2880	J-08S	0.071	Manual	Т
679213.7730	3083224.9730	J-09S	0.072	Manual	Т
679280.5440	3083305.6810	J-10S	0.073	Manual	Т
679268.7700	3083200.3260	J-11S	0.083	Manual	Т
679301.1600	3083254.0340	J-12S	0.072	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte					Para	ameter	
	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

b This value is automatically calculated by VSP based upon the user defined value of β.

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples										
AL=0.	4	α=	:5	α=	10	α=	15				
AL=U.	1	s=6	s=3	s=6 s=3		s=6	s=3				
	β=5	3895984	973997	3082986	770748	2588149	647038				
LBGR=90	β=10	3082987	770748	2365020	591256	1934301	483576				
	β=15	2588150	647039	1934301	483576	1546841	386711				
	β=5	973997	243501	770748	192688	647038	161760				
LBGR=80	β=10	770748	192688	591256	147815	483576	120895				
	β=15	647039	161761	483576	120895	386711	96679				
	β=5	432889	108224	342555	85640	287573	71894				
LBGR=70	β=10	342556	85640	262781	65696	214923	53732				
	β=15	287574	71895	214923	53732	171872	42969				

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST IN	COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples								
Field collection costs		\$100.00	\$2,100.00								
Analytical costs	\$400.00	\$400.00	\$8,400.00								
Sum of Field & Analytical costs		\$500.00	\$10,500.00								
Fixed planning and validation costs			\$1,000.00								
Total cost			\$11,500.00								

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.064	0.066	0.067	0.07	0.07	0.07	0.07	0.07	0.071	0.071

10	0.071	0.071	0.071	0.072	0.072	0.072	0.072	0.072	0.072	0.072
20	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.074
30	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.075	0.075
40	0.075	0.076	0.076	0.076	0.076	0.076	0.076	0.076	0.077	0.077
50	0.077	0.078	0.079	0.079	0.079	0.082	0.083	0.085	0.085	0.33
60	0.83									

	SUMMARY STATISTICS								
	n					61			
	Mi	n				0.064			
	Ма	X				0.83			
Range						0.766			
Mean					0	.090607	•		
	Median				0.074				
	Variance			0.010353					
	StdE)ev		0.10175					
	Std E	rror		0.013028					
	Skewi	ness				6.832			
Int	Interquartile Range			0.004					
	Pe				ercentiles				
1%	5%	10%	25%	50% 75% 90% 95% 99%					
0.064	0.0673	0.07	0.072	0.074	0.076	0.0814	0.085	0.83	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	7.205	3.2	Yes			

The test statistic 7.205 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS				
1	0.83			

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the

suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.4078
Lilliefors 5% Critical Value	0.1153

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4892			
Lilliefors 5% Critical Value	0.1134			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.1124
95% Non-Parametric (Chebyshev) UCL	0.1474

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1474) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=61 data, AL is the action level or threshold (0,1).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=60 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic	Critical Value t _{0.95}	Null Hypothesis			
-0.72105	1.6706	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
59	37	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold						
Type of Sampling Design	Parametric						
Sample Placement (Location) in the Field	Simple random sampling						
Working (Null) Hypothesis	The mean value at the site exceeds the threshold						
Formula for calculating number of sampling locations	Student's t-test						
Calculated total number of samples	21						
Number of samples on map ^a	60						
Number of selected sample areas b	5						
Specified sampling area ^c	941426.62 m ²						
Total cost of sampling d	\$11,500.00						

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1							
X Coord	Y Coord	Label	Value	Туре	Historical			
679149.4920	3082933.0980	J-13S	0.077	Manual	Т			
679279.6830	3083075.4290	J-14S	0.077	Manual	Т			
679261.0980	3083016.3510	J-15S	0.07	Manual	Т			
679222.6340	3082840.1720	J-16S	0.072	Manual	Т			
679293.5600	3082950.4980	J-17S	0.079	Manual	Т			
679360.5700	3083026.4980	J-18S	0.074	Manual	Т			
679343.5810	3082969.5980	J-19S	0.077	Manual	Т			
679382.8640	3083009.1130	J-20S	0.83	Manual	Т			
679335.0020	3082941.1720	J-21S	0.073	Manual	Т			
679252.7130	3082781.0290	J-22S	0.072	Manual	Т			
679297.0010	3082840.6970	J-23S	0.071	Manual	Т			
679394.8070	3082971.8300	J-24S	0.073	Manual	Т			
679146.6460	3082549.7640	J-25S	0.064	Manual	Т			
679224.5850	3082683.1400	J-26S	0.072	Manual	Т			
679169.0760	3082537.3510	J-27S	0.072	Manual	Т			
679272.0040	3082652.6750	J-28S	0.073	Manual	Т			

679329.4380 3082711.0960 J-29S 0.071 Manual T 679374.4420 3082791.3300 J-30S 0.074 Manual T 679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.074 Manual T 679497.3310 3082886.8990 J-40S 0.074 Manual T 679524.3310 3082872.3490 J-47S 0.076 Manual T 679994.9690						
679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082607.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.074 Manual T 679497.3310 3082886.8990 J-40S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679924.8150 3082872.3490 J-41S 0.072 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580	679329.4380	3082711.0960	J-29S	0.071	Manual	Т
679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082607.5270 J-36S 0.074 Manual T 679470.3570 3082731.6820 J-37S 0.071 Manual T 679497.3310 3082840.3960 J-38S 0.078 Manual T 679497.3310 3082886.8990 J-40S 0.074 Manual T 679524.3310 30828872.3490 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680141.8730	679374.4420	3082791.3300	J-30S	0.074	Manual	Т
679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.076 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083115.5330 J-50S 0.076 Manual T 680141.8730	679410.1490	3082845.8460	J-31S	0.079	Manual	Т
679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.074 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680141.8730 3082729.7460 J-51S 0.076 Manual T 680170.5600	679453.4760	3082914.1150	J-32S	0.076	Manual	Т
679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679124.7500	679495.8840	3082940.9730	J-33S	0.073	Manual	Т
679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680057.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3083080.8800 J-51S 0.074 Manual T 680170.5600 3083084.6740 J-53S 0.075 Manual T 679124.7500 3082617.3010 Composite 1 0.074 Manual T	679304.6530	3082548.6880	J-34S	0.073	Manual	Т
679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3082729.7460 J-51S 0.074 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 </td <td>679342.7410</td> <td>3082605.3190</td> <td>J-35S</td> <td>0.076</td> <td>Manual</td> <td>Т</td>	679342.7410	3082605.3190	J-35S	0.076	Manual	Т
679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.	679382.8900	3082667.5270	J-36S	0.074	Manual	Т
679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679433.9450	3082731.6820	J-37S	0.071	Manual	Т
679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679470.3570	3082776.7350	J-38S	0.078	Manual	Т
679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679497.3310	3082840.3960	J-39S	0.074	Manual	Т
679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 3 0.076 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679524.3310	3082886.8990	J-40S	0.074	Manual	Т
679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 3 0.076 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679560.6070	3082897.2580	J-41S	0.072	Manual	Т
680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679924.8150	3082872.3490	J-47S	0.076	Manual	Т
680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679994.9690	3082983.5100	J-48S	0.076	Manual	Т
679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680057.6580	3083072.0750	J-49S	0.079	Manual	Т
680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680077.3540	3083115.5330	J-50S	0.076	Manual	Т
680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679827.1150	3082729.7460	J-51S	0.074	Manual	Т
679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680141.8730	3083080.8800	J-52S	0.076	Manual	Т
679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680170.5600	3083064.6740	J-53S	0.075	Manual	Т
679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679129.3320	3082802.5620	Composite 1	0.074	Manual	Т
679240.6200 3082579.3320 Composite 2 0.075 Manual T	679124.7500	3082617.3010	Composite 3	0.076	Manual	Т
<u>'</u>	679107.0750	3082512.5600	Composite 4	0.074	Manual	Т
679687.6145 3083602.0759 Composite 5 0.073 Random	679240.6200	3082579.3320	Composite 2	0.075	Manual	Т
1. 222. 12. 13 3000002.01 00 Composite 0 0.010 Random	679687.6145	3083602.0759	Composite 5	0.073	Random	

Area: Area 2						
X Coord	Y Coord	Label	Value	Туре	Historical	
680320.6560	3082842.6400	Composite 5	0.073	Manual	Т	
680357.8357	3082854.0284	J-62S	0.073	Random		

Area: Area 3						
X Coord	Y Coord	Label	Value	Туре	Historical	
679356.9310	3083064.0350	J-62S	0.073	Manual	Т	
679396.8510	3083038.0640	J-64S	0.074	Manual	Т	
679386.3850	3083044.5490	J-63S	0.071	Manual	Т	

Area: Area 4					
X Coord	Y Coord	Label	Value	Туре	Historical
679175.7550	3083152.6270	J-65S	0.066	Manual	Т
679113.1200	3083190.3150	J-66S	0.067	Manual	Т

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.085	Manual	Т
679104.2450	3083223.2620	J-02S	0.07	Manual	Т
679155.0740	3083294.6960	J-03S	0.082	Manual	Т
679171.2970	3083289.7960	J-04S	0.33	Manual	Т
679225.8560	3083359.9740	J-05S	0.075	Manual	Т
679164.8060	3083214.7100	J-06S	0.07	Manual	Т
679242.7260	3083326.5280	J-07S	0.07	Manual	Т
679181.2750	3083178.2880	J-08S	0.071	Manual	Т
679213.7730	3083224.9730	J-09S	0.072	Manual	Т
679280.5440	3083305.6810	J-10S	0.073	Manual	Т
679268.7700	3083200.3260	J-11S	0.083	Manual	Т
679301.1600	3083254.0340	J-12S	0.072	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .


The values of these inputs that result in the calculated number of sampling locations are:

Analysta					Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

b This value is automatically calculated by VSP based upon the user defined value of β.

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples						
AL=8.87	74 5 4	α=	=5	α=	10	α=	15
AL=0.07	154	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	497	126	393	99	330	83
LBGR=90	β=10	394	100	302	76	247	62
	β=15	331	84	247	63	198	50
	β=5	126	33	99	26	83	22
LBGR=80	β=10	100	26	76	20	62	16
	β=15	84	22	63	17	50	13
	β=5	57	16	45	12	38	10
LBGR=70	β=10	45	13	35	10	28	8
	β=15	38	11	29	8	23	6

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST IN	COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples				
Field collection costs		\$100.00	\$2,100.00				
Analytical costs	\$400.00	\$400.00	\$8,400.00				
Sum of Field & Analytical costs		\$500.00	\$10,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$11,500.00				

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.064	0.066	0.067	0.07	0.07	0.07	0.07	0.07	0.071

10	0.071	0.071	0.071	0.071	0.072	0.072	0.072	0.072	0.072	0.072
20	0.072	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073
30	0.073	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074
40	0.075	0.075	0.075	0.076	0.076	0.076	0.076	0.076	0.076	0.076
50	0.077	0.077	0.077	0.078	0.079	0.079	0.079	0.082	0.083	0.085
60	0.085	0.33	0.83							

		SI	JMMAF	RY STA	TISTIC	cs		
	n			63				
	Mi	n				0		
	Ма	ìх				0.83		
	Ran	ge				0.83		
	Ме	an			0	.088889)	
	Med	ian				0.074		
	Varia	nce		0.010153				
	StdI	Dev		0.10076				
	Std E	rror		0.012695				
	Skew	ness				6.8407		
ln	terquarti	ile Raı	nge			0.004		
			Pe	rcentiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.0662	0.07	0.072	0.074	0.076	0.0808	0.085	0.83

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	7.355	3.218	Yes		

The test statistic 7.355 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	0.83

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the

suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.3953
Lilliefors 5% Critical Value	0.1125

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic 0.4836					
Lilliefors 5% Critical Value	0.1116				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.1101
95% Non-Parametric (Chebyshev) UCL	0.1442

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1442) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=63 data,

AL is the action level or threshold (8.87154).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=62 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-691.82	1.6698	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+) 95% Critical Value Null Hypothesis					
63	39	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	60					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679149.4920	3082933.0980	J-13S	0.077	Manual	Т			
679279.6830	3083075.4290	J-14S	0.077	Manual	Т			
679261.0980	3083016.3510	J-15S	0.07	Manual	Т			
679222.6340	3082840.1720	J-16S	0.072	Manual	Т			
679293.5600	3082950.4980	J-17S	0.079	Manual	Т			
679360.5700	3083026.4980	J-18S	0.074	Manual	Т			
679343.5810	3082969.5980	J-19S	0.077	Manual	Т			
679382.8640	3083009.1130	J-20S	0.83	Manual	Т			
679335.0020	3082941.1720	J-21S	0.073	Manual	Т			
679252.7130	3082781.0290	J-22S	0.072	Manual	Т			
679297.0010	3082840.6970	J-23S	0.071	Manual	Т			
679394.8070	3082971.8300	J-24S	0.073	Manual	Т			
679146.6460	3082549.7640	J-25S	0.064	Manual	Т			
679224.5850	3082683.1400	J-26S	0.072	Manual	Т			
679169.0760	3082537.3510	J-27S	0.072	Manual	Т			
679272.0040	3082652.6750	J-28S	0.073	Manual	Т			

679329.4380 3082711.0960 J-29S 0.071 Manual T 679374.4420 3082791.3300 J-30S 0.074 Manual T 679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 308276.7350 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.074 Manual T 679497.3310 3082886.8990 J-40S 0.074 Manual T 679524.3310 3082897.2580 J-41S 0.072 Manual T 679924.8150						
679410.1490 3082845.8460 J-31S 0.079 Manual T 679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082607.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.074 Manual T 679497.3310 3082886.8990 J-40S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679924.8150 3082872.3490 J-41S 0.072 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580	679329.4380	3082711.0960	J-29S	0.071	Manual	Т
679453.4760 3082914.1150 J-32S 0.076 Manual T 679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082607.5270 J-36S 0.074 Manual T 679470.3570 3082731.6820 J-37S 0.071 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679924.8150 3082872.3490 J-41S 0.072 Manual T 679994.9690 3082872.3490 J-47S 0.076 Manual T 680057.6580 3083072.0750 J-48S 0.076 Manual T 680057.6580 3083115.5330 J-50S 0.076 Manual T 680141.8730	679374.4420	3082791.3300	J-30S	0.074	Manual	Т
679495.8840 3082940.9730 J-33S 0.073 Manual T 679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730	679410.1490	3082845.8460	J-31S	0.079	Manual	Т
679304.6530 3082548.6880 J-34S 0.073 Manual T 679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.074 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680141.8730 3082729.7460 J-51S 0.076 Manual T 680170.5600	679453.4760	3082914.1150	J-32S	0.076	Manual	Т
679342.7410 3082605.3190 J-35S 0.076 Manual T 679382.8900 3082667.5270 J-36S 0.074 Manual T 679470.3570 3082731.6820 J-37S 0.071 Manual T 679497.3310 3082840.3960 J-38S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3083080.8800 J-51S 0.074 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679124.7500	679495.8840	3082940.9730	J-33S	0.073	Manual	Т
679382.8900 3082667.5270 J-36S 0.074 Manual T 679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680057.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3083080.8800 J-51S 0.074 Manual T 680170.5600 3083084.6740 J-53S 0.075 Manual T 679124.7500 3082617.3010 Composite 1 0.074 Manual T	679304.6530	3082548.6880	J-34S	0.073	Manual	Т
679433.9450 3082731.6820 J-37S 0.071 Manual T 679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.076 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 680141.8730 3082729.7460 J-51S 0.074 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082617.3010 Composite 1 0.074 Manual T 679107.0750 </td <td>679342.7410</td> <td>3082605.3190</td> <td>J-35S</td> <td>0.076</td> <td>Manual</td> <td>Т</td>	679342.7410	3082605.3190	J-35S	0.076	Manual	Т
679470.3570 3082776.7350 J-38S 0.078 Manual T 679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.	679382.8900	3082667.5270	J-36S	0.074	Manual	Т
679497.3310 3082840.3960 J-39S 0.074 Manual T 679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082617.3010 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679433.9450	3082731.6820	J-37S	0.071	Manual	Т
679524.3310 3082886.8990 J-40S 0.074 Manual T 679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679470.3570	3082776.7350	J-38S	0.078	Manual	Т
679560.6070 3082897.2580 J-41S 0.072 Manual T 679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 2 0.075 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679497.3310	3082840.3960	J-39S	0.074	Manual	Т
679924.8150 3082872.3490 J-47S 0.076 Manual T 679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679524.3310	3082886.8990	J-40S	0.074	Manual	Т
679994.9690 3082983.5100 J-48S 0.076 Manual T 680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679107.0750 3082512.5600 Composite 3 0.076 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679560.6070	3082897.2580	J-41S	0.072	Manual	Т
680057.6580 3083072.0750 J-49S 0.079 Manual T 680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679924.8150	3082872.3490	J-47S	0.076	Manual	Т
680077.3540 3083115.5330 J-50S 0.076 Manual T 679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679994.9690	3082983.5100	J-48S	0.076	Manual	Т
679827.1150 3082729.7460 J-51S 0.074 Manual T 680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680057.6580	3083072.0750	J-49S	0.079	Manual	Т
680141.8730 3083080.8800 J-52S 0.076 Manual T 680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680077.3540	3083115.5330	J-50S	0.076	Manual	Т
680170.5600 3083064.6740 J-53S 0.075 Manual T 679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679827.1150	3082729.7460	J-51S	0.074	Manual	Т
679129.3320 3082802.5620 Composite 1 0.074 Manual T 679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680141.8730	3083080.8800	J-52S	0.076	Manual	Т
679124.7500 3082617.3010 Composite 3 0.076 Manual T 679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	680170.5600	3083064.6740	J-53S	0.075	Manual	Т
679107.0750 3082512.5600 Composite 4 0.074 Manual T 679240.6200 3082579.3320 Composite 2 0.075 Manual T	679129.3320	3082802.5620	Composite 1	0.074	Manual	Т
679240.6200 3082579.3320 Composite 2 0.075 Manual T	679124.7500	3082617.3010	Composite 3	0.076	Manual	Т
<u>'</u>	679107.0750	3082512.5600	Composite 4	0.074	Manual	Т
070074 0000 0000450 0400 0	679240.6200	3082579.3320	Composite 2	0.075	Manual	Т
679974.2022 3083152.2432 Composite 5 0.073 Random	679974.2022	3083152.2432	Composite 5	0.073	Random	

Area: Area 2						
X Coord Y Coord Label Value Type Historic						
680320.6560	3082842.6400	Composite 5	0.073	Manual	Т	

Area: Area 3							
X Coord	X Coord Y Coord Label Value Type						
679356.9310	3083064.0350	J-62S	0.073	Manual	Т		
679396.8510	3083038.0640	J-64S	0.074	Manual	Т		
679386.3850	3083044.5490	J-63S	0.071	Manual	Т		

Area: Area 4							
X Coord	Y Coord	Label	Value	Туре	Historical		
679175.7550	3083152.6270	J-65S	0.066	Manual	Т		
679113.1200	3083190.3150	J-66S	0.067	Manual	Т		
679096.4233	3083190.2180	J-01S	0.085	Random			

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.085	Manual	Т
679104.2450	3083223.2620	J-02S	0.07	Manual	Т
679155.0740	3083294.6960	J-03S	0.082	Manual	Т
679171.2970	3083289.7960	J-04S	0.33	Manual	Т
679225.8560	3083359.9740	J-05S	0.075	Manual	Т
679164.8060	3083214.7100	J-06S	0.07	Manual	Т
679242.7260	3083326.5280	J-07S	0.07	Manual	Т
679181.2750	3083178.2880	J-08S	0.071	Manual	Т
679213.7730	3083224.9730	J-09S	0.072	Manual	Т
679280.5440	3083305.6810	J-10S	0.073	Manual	Т
679268.7700	3083200.3260	J-11S	0.083	Manual	Т
679301.1600	3083254.0340	J-12S	0.072	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta		Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

b This value is automatically calculated by VSP based upon the user defined value of β.

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=0.	41.04		:5	α=	10	α=15	
AL=U.	1	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	3895984	973997	3082986	770748	2588149	647038
LBGR=90	β=10	3082987	770748	2365020	591256	1934301	483576
	β=15	2588150	647039	1934301	483576	1546841	386711
	β=5	973997	243501	770748	192688	647038	161760
LBGR=80	β=10	770748	192688	591256	147815	483576	120895
	β=15	647039	161761	483576	120895	386711	96679
	β=5	432889	108224	342555	85640	287573	71894
LBGR=70	β=10	342556	85640	262781	65696	214923	53732
	β=15	287574	71895	214923	53732	171872	42969

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0.064	0.066	0.067	0.07	0.07	0.07	0.07	0.07	0.071	0.071

10	0.071	0.071	0.071	0.072	0.072	0.072	0.072	0.072	0.072	0.072
20	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073	0.073
30	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.074	0.075
40	0.075	0.075	0.076	0.076	0.076	0.076	0.076	0.076	0.076	0.077
50	0.077	0.077	0.078	0.079	0.079	0.079	0.082	0.083	0.085	0.085
60	0.33	0.83								

	SUMMARY STATISTICS							
	n		62					
	Mir	1				0.064		
	Max	K				0.83		
	Rang	ge				0.766		
	Mea	n			0	.090323	}	
	Medi	an		0.074				
	Variance			0.010188				
StdDev				0.10094				
	Std E	ror		0.012819				
	Skewness					6.8884		
In	Interquartile Range				0.004			
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.064	0.06745	0.07	0.072	0.074	0.076	0.0811	0.085	0.83

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	7.328	3.212	Yes		

The test statistic 7.328 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	0.83	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the

suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Lilliefors Test Statistic	0.4083		
Lilliefors 5% Critical Value	0.1134		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots


Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.





For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Lilliefors Test Statistic	0.4888		
Lilliefors 5% Critical Value	0.1125		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	0.1117
95% Non-Parametric (Chebyshev) UCL	0.1462

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.1462) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=62 data, AL is the action level or threshold (0.1).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=61 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
-0.75494	1.6702	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
60	38	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	60
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



	Area: Area 1											
X Coord	Y Coord	Label	Value	Туре	Historical							
679149.4920	3082933.0980	J-13S	4.9	Manual	Т							
679279.6830	3083075.4290	J-14S	0.6	Manual	Т							
679261.0980	3083016.3510	J-15S	3.4	Manual	Т							
679222.6340	3082840.1720	J-16S	3.2	Manual	Т							
679293.5600	3082950.4980	J-17S	2.4	Manual	Т							
679360.5700	3083026.4980	J-18S	3.2	Manual	Т							
679343.5810	3082969.5980	J-19S	15	Manual	Т							
679382.8640	3083009.1130	J-20S	2.5	Manual	Т							
679335.0020	3082941.1720	J-21S	0.59	Manual	Т							
679252.7130	3082781.0290	J-22S	4.1	Manual	Т							
679297.0010	3082840.6970	J-23S	3.5	Manual	Т							
679394.8070	3082971.8300	J-24S	1.2	Manual	Т							
679146.6460	3082549.7640	J-25S	7.4	Manual	Т							
679224.5850	3082683.1400	J-26S	1.7	Manual	Т							
679169.0760	3082537.3510	J-27S	3.7	Manual	Т							
679272.0040	3082652.6750	J-28S	6.1	Manual	Т							

679329.4380 3082711.0960 J-29S 2.7 Manual T 679374.4420 3082791.3300 J-30S 2.2 Manual T 679410.1490 3082845.8460 J-31S 0.76 Manual T 679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082886.8990 J-40S 2.3 Manual T 679524.3310 3082886.8990 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 680057.6580					
679410.1490 3082845.8460 J-31S 0.76 Manual T 679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679433.9450 3082667.5270 J-36S 6 Manual T 679470.3570 3082776.7350 J-37S 8.8 Manual T 679497.3310 3082840.3960 J-38S 2.5 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679524.8150 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680077.3540 3083115.5330 <td>679329.4380</td> <td>3082711.0960</td> <td>J-29S</td> <td>2.7</td> <td>Manual T</td>	679329.4380	3082711.0960	J-29S	2.7	Manual T
679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679524.8150 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083115.5330 J-50S 3.2 Manual T 680141.8730 3	679374.4420	3082791.3300	J-30S	2.2	Manual T
679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 6799994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680141.8730 3083080.8800 J-51S 2.2 Manual T 680141.8730	679410.1490	3082845.8460	J-31S	0.76	Manual T
679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 680141.8730 3083084.6740 J-53S 3.9 Manual T 680170.5600 3	679453.4760	3082914.1150	J-32S	2.9	Manual T
679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3082729.7460 J-51S 2.2 Manual T 680141.8730 3082802.5620 J-51S 2.2 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3	679495.8840	3082940.9730	J-33S	1.9	Manual T
679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 680141.8730 3083080.8800 J-51S 2.2 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 2 3 Manual T	679304.6530	3082548.6880	J-34S	1.5	Manual T
679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680170.5600 3083080.8800 J-52S 4 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679342.7410	3082605.3190	J-35S	1.8	Manual T
679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679382.8900	3082667.5270	J-36S	6	Manual T
679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679433.9450	3082731.6820	J-37S	8.8	Manual T
679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679470.3570	3082776.7350	J-38S	2.5	Manual T
679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679497.3310	3082840.3960	J-39S	1.4	Manual T
679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679524.3310	3082886.8990	J-40S	2.3	Manual T
679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679560.6070	3082897.2580	J-41S	2.2	Manual T
680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679924.8150	3082872.3490	J-47S	2.7	Manual T
680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679994.9690	3082983.5100	J-48S	3.4	Manual T
679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680057.6580	3083072.0750	J-49S	3.6	Manual T
680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680077.3540	3083115.5330	J-50S	3.2	Manual T
680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679827.1150	3082729.7460	J-51S	2.2	Manual T
679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680141.8730	3083080.8800	J-52S	4	Manual T
679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680170.5600	3083064.6740	J-53S	3.9	Manual T
679124.7500 3082617.3010 Composite 3 2.1 Manual T	679129.3320	3082802.5620	Composite 1	1.6	Manual T
	679240.6200	3082579.3320	Composite 2	3	Manual T
679107.0750 3082512.5600 Composite 4 1.6 Manual T	679124.7500	3082617.3010	Composite 3	2.1	Manual T
	679107.0750	3082512.5600	Composite 4	1.6	Manual T

	Area: Area 2									
X Coord	Y Coord	Label	Value	Туре	Historical					
680320.6560	3082842.6400	Composite 5	4.4	Manual	Т					

Area: Area 3											
X Coord	Y Coord	Label	Value	Туре	Historical						
679356.9310	3083064.0350	J-62S	2.1	Manual	Т						
679386.3850	3083044.5490	J-63S	4	Manual	Т						
679396.8510	3083038.0640	J-64S	2.3	Manual	Т						
679389.4539	3083039.3751	J-65S	0.9	Random							

Area: Area 4										
X Coord	Y Coord	Label	Value	Туре	Historical					
679175.7550	3083152.6270	J-65S	0.9	Manual	Т					
679113.1200	3083190.3150	J-66S	0.53	Manual	Т					

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.63	Manual	Т
679104.2450	3083223.2620	J-02S	3.9	Manual	Т
679155.0740	3083294.6960	J-03S	1.2	Manual	Т
679171.2970	3083289.7960	J-04S	2.1	Manual	Т
679225.8560	3083359.9740	J-05S	0.8	Manual	Т
679164.8060	3083214.7100	J-06S	3.7	Manual	Т
679242.7260	3083326.5280	J-07S	4.3	Manual	Т
679181.2750	3083178.2880	J-08S	5.2	Manual	Т
679213.7730	3083224.9730	J-09S	1.8	Manual	Т
679280.5440	3083305.6810	J-10S	1	Manual	Т
679268.7700	3083200.3260	J-11S	0.98	Manual	Т
679301.1600	3083254.0340	J-12S	0.58	Manual	Т
679232.5619	3083288.7154		0	Random	

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

is the width of the gray region,

is the acceptable probability of incorrectly concluding the site mean is less than the threshold.

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold.

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is $1-\alpha$, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\beta}^{-\alpha}$ is 1- β .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_		Parameter						
Analyte	n	S	Δ	α	α β $Z_{1-\alpha}$ α		Z_{1-β} b		
	21	3	2	0.05	0.1	1.64485	1.28155		


^a This value is automatically calculated by VSP based upon the user defined value of α .

^b This value is automatically calculated by VSP based upon the user defined value of ß.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.





Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30

or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),

- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples										
AL=10	n	α:	=5	α=	10	α=	15			
AL=I	J	s=6	s=3	s=6	s=3	s=6	s=3			
	β=5	391	99	310	78	260	66			
LBGR=90	β=10	310	79	238	60	194	49			
	β=15	261	67	195	50	156	40			
	β=5	99	26	78	21	66	17			
LBGR=80	β=10	79	21	60	16	49	13			
	β=15	67	18	50	13	40	11			
	β=5	45	13	36	10	30	8			
LBGR=70	LBGR=70 β=10		10	28	8	23	6			
	β=15	31	9	23	7	18	5			

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION										
Cost Details	Per Analysis	Per Sample	21 Samples							
Field collection costs		\$100.00	\$2,100.00							
Analytical costs	\$400.00	\$400.00	\$8,400.00							
Sum of Field & Analytical costs		\$500.00	\$10,500.00							
Fixed planning and validation costs			\$1,000.00							
Total cost			\$11,500.00							

Data Analysis

The following data points were entered by the user for analysis.

Rank 1 2 3 4 5 6 7 8 9	10	9	8 9	8	7	6	5	4	3	2	1	
------------------------	----	---	-----	---	---	---	---	---	---	---	---	--

0	0	0.53	0.58	0.59	0.6	0.63	0.76	0.8	0.9	0.9
10	0.98	1	1.2	1.2	1.4	1.5	1.6	1.6	1.7	1.8
20	1.8	1.9	2.1	2.1	2.1	2.1	2.2	2.2	2.2	2.3
30	2.3	2.4	2.5	2.5	2.7	2.7	2.9	3	3.2	3.2
40	3.2	3.4	3.4	3.5	3.6	3.7	3.7	3.9	3.9	4
50	4	4.1	4.3	4.4	4.4	4.9	5.2	6	6.1	7.4
60	8.8	15								

	SUMMARY STATISTICS							
	n)				62		
	Mi	in				0		
	Ma	ах				15		
	Rar	ige				15		
	Me	an				2.896	3	
	Med	lian				2.35		
	Varia	nce		5.3925				
	StdI	Dev		2.3222				
	Std E	Error		0.29492				
	Skew	ness		2.7155				
In	Interquartile Range			2.275				
	Percentiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.5815	0.669	1.475	2.35	3.75	5.11	7.205	15

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST							
k	k Test Statistic R _k 5% Critical Value C _k Significant?							
1	5.193	3.2	Yes					

The test statistic 5.193 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS					
1	15				

Because Rosner's test can be used only when the data without the suspected outlier are approximately normally

distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Lilliefors Test Statistic	0.1061					
Lilliefors 5% Critical Value	0.1153					

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test cannot reject the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do appear to follow a normal distribution at the 5% level of significance.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/guality/ga-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic 0.1457					
Lilliefors 5% Critical Value 0.1125					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN	
95% Parametric UCL	3.389
95% Non-Parametric (Chebyshev) UCL	4.182

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.182) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=62 data, AL is the action level or threshold (10).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=61 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic Critical Value $t_{0.95}$ Null Hypothesis							
-24.087	1.6702	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
61	38	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field and a table that lists sampling location coordinates are also provided below.


SUMMARY OF SAMPLING DESIGN						
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	60					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Area: Area 1								
X Coord	Y Coord	Label	Value	Туре	Historical			
679149.4920	3082933.0980	J-13S	4.9	Manual	Т			
679279.6830	3083075.4290	J-14S	0.6	Manual	Т			
679261.0980	3083016.3510	J-15S	3.4	Manual	Т			
679222.6340	3082840.1720	J-16S	3.2	Manual	Т			
679293.5600	3082950.4980	J-17S	2.4	Manual	Т			
679360.5700	3083026.4980	J-18S	3.2	Manual	Т			
679343.5810	3082969.5980	J-19S	15	Manual	Т			
679382.8640	3083009.1130	J-20S	2.5	Manual	Т			
679335.0020	3082941.1720	J-21S	0.59	Manual	Т			
679252.7130	3082781.0290	J-22S	4.1	Manual	Т			
679297.0010	3082840.6970	J-23S	3.5	Manual	Т			
679394.8070	3082971.8300	J-24S	1.2	Manual	Т			
679146.6460	3082549.7640	J-25S	7.4	Manual	Т			
679224.5850	3082683.1400	J-26S	1.7	Manual	Т			
679169.0760	3082537.3510	J-27S	3.7	Manual	Т			
679272.0040	3082652.6750	J-28S	6.1	Manual	Т			

679329.4380 3082711.0960 J-29S 2.7 Manual T 679374.4420 3082791.3300 J-30S 2.2 Manual T 679410.1490 3082845.8460 J-31S 0.76 Manual T 679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679497.3310 3082840.3960 J-38S 2.5 Manual T 679497.3310 3082886.8990 J-40S 2.3 Manual T 679524.3310 3082887.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 680057.6580					
679410.1490 3082845.8460 J-31S 0.76 Manual T 679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 <td>679329.4380</td> <td>3082711.0960</td> <td>J-29S</td> <td>2.7</td> <td>Manual T</td>	679329.4380	3082711.0960	J-29S	2.7	Manual T
679453.4760 3082914.1150 J-32S 2.9 Manual T 679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679470.3570 3082776.7350 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679470.3570 3082840.3960 J-39S 1.4 Manual T 679497.3310 3082886.8990 J-40S 2.3 Manual T 679524.3310 3082887.23490 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679924.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083015.5330 J-50S 3.2 Manual T 680141.8730	679374.4420	3082791.3300	J-30S	2.2	Manual T
679495.8840 3082940.9730 J-33S 1.9 Manual T 679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680141.8730 3082802.5630 J-51S 2.2 Manual T 680170.5600 3	679410.1490	3082845.8460	J-31S	0.76	Manual T
679304.6530 3082548.6880 J-34S 1.5 Manual T 679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 308	679453.4760	3082914.1150	J-32S	2.9	Manual T
679342.7410 3082605.3190 J-35S 1.8 Manual T 679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 680141.8730 30828272.7460 J-51S 2.2 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320	679495.8840	3082940.9730	J-33S	1.9	Manual T
679382.8900 3082667.5270 J-36S 6 Manual T 679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680170.5600 3083080.8800 J-52S 4 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 <	679304.6530	3082548.6880	J-34S	1.5	Manual T
679433.9450 3082731.6820 J-37S 8.8 Manual T 679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679342.7410	3082605.3190	J-35S	1.8	Manual T
679470.3570 3082776.7350 J-38S 2.5 Manual T 679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679382.8900	3082667.5270	J-36S	6	Manual T
679497.3310 3082840.3960 J-39S 1.4 Manual T 679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679433.9450	3082731.6820	J-37S	8.8	Manual T
679524.3310 3082886.8990 J-40S 2.3 Manual T 679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679470.3570	3082776.7350	J-38S	2.5	Manual T
679560.6070 3082897.2580 J-41S 2.2 Manual T 679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679497.3310	3082840.3960	J-39S	1.4	Manual T
679924.8150 3082872.3490 J-47S 2.7 Manual T 679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679524.3310	3082886.8990	J-40S	2.3	Manual T
679994.9690 3082983.5100 J-48S 3.4 Manual T 680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679560.6070	3082897.2580	J-41S	2.2	Manual T
680057.6580 3083072.0750 J-49S 3.6 Manual T 680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679924.8150	3082872.3490	J-47S	2.7	Manual T
680077.3540 3083115.5330 J-50S 3.2 Manual T 679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679994.9690	3082983.5100	J-48S	3.4	Manual T
679827.1150 3082729.7460 J-51S 2.2 Manual T 680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680057.6580	3083072.0750	J-49S	3.6	Manual T
680141.8730 3083080.8800 J-52S 4 Manual T 680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680077.3540	3083115.5330	J-50S	3.2	Manual T
680170.5600 3083064.6740 J-53S 3.9 Manual T 679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	679827.1150	3082729.7460	J-51S	2.2	Manual T
679129.3320 3082802.5620 Composite 1 1.6 Manual T 679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680141.8730	3083080.8800	J-52S	4	Manual T
679240.6200 3082579.3320 Composite 2 3 Manual T 679124.7500 3082617.3010 Composite 3 2.1 Manual T	680170.5600	3083064.6740	J-53S	3.9	Manual T
679124.7500 3082617.3010 Composite 3 2.1 Manual T	679129.3320	3082802.5620	Composite 1	1.6	Manual T
<u>'</u>	679240.6200	3082579.3320	Composite 2	3	Manual T
679107.0750 3082512.5600 Composite 4 1.6 Manual T	679124.7500	3082617.3010	Composite 3	2.1	Manual T
	679107.0750	3082512.5600	Composite 4	1.6	Manual T

	Area: Area 2								
X Coord	Y Coord	Label	Value	Туре	Historical				
680320.6560	3082842.6400	Composite 5	4.4	Manual	Т				
680445.0613	3082942.1178	J-62S	2.1	Random					
680358.3341	3082778.8501	J-63S	4	Random					

Area: Area 3							
X Coord	Y Coord	Label	Value	Туре	Historical		
679356.9310	3083064.0350	J-62S	2.1	Manual	Т		
679386.3850	3083044.5490	J-63S	4	Manual	Т		
679396.8510	3083038.0640	J-64S	2.3	Manual	Т		

Area: Area 4							
X Coord	Y Coord	Label	Value	Туре	Historical		
679175.7550	3083152.6270	J-65S	0.9	Manual	Т		
679113.1200	3083190.3150	J-66S	0.53	Manual	Т		

Area: Area 5

X Coord	Y Coord	Label	Value	Туре	Historical
679133.4290	3083306.3130	J-01S	0.63	Manual	Т
679104.2450	3083223.2620	J-02S	3.9	Manual	Т
679155.0740	3083294.6960	J-03S	1.2	Manual	Т
679171.2970	3083289.7960	J-04S	2.1	Manual	Т
679225.8560	3083359.9740	J-05S	0.8	Manual	Т
679164.8060	3083214.7100	J-06S	3.7	Manual	Т
679242.7260	3083326.5280	J-07S	4.3	Manual	Т
679181.2750	3083178.2880	J-08S	5.2	Manual	Т
679213.7730	3083224.9730	J-09S	1.8	Manual	Т
679280.5440	3083305.6810	J-10S	1	Manual	Т
679268.7700	3083200.3260	J-11S	0.98	Manual	Т
679301.1600	3083254.0340	J-12S	0.58	Manual	Т

Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Lambda^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

is the number of samples.

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

is the acceptable probability of incorrectly concluding the site mean exceeds the threshold, is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:


Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	$Z_{1-\alpha}^{a}$	Z_{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155

^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,

- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

	Number of Samples						
A1 -0/	4	α	=5	α=	:10	α=	:15
AL=8	1	s=6	s=3	s=6	s=3	s=6	s=3
	β=5	8	3	6	2	5	2
LBGR=90	β=10	7	3	5	2	4	2
	β=15	6	3	4	2	3	2
	β=5	3	2	2	2	2	1
LBGR=80	β=10	3	2	2	2	2	1
	β=15	3	2	2	2	2	1
	β=5	3	2	2	1	1	1
LBGR=70	β=10	2	2	2	1	1	1
	β=15	2	2	2	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST IN	COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

The following data points were entered by the user for analysis.

Rank	1	2	3	4	5	6	7	8	9	10
0	0	0.53	0.58	0.59	0.6	0.63	0.63	0.76	0.8	0.9

10	0.9	0.98	1	1.2	1.2	1.4	1.5	1.6	1.6	1.7
20	1.8	1.8	1.9	2.1	2.1	2.1	2.1	2.2	2.2	2.2
30	2.3	2.3	2.4	2.5	2.5	2.7	2.7	2.9	3	3.2
40	3.2	3.2	3.4	3.4	3.5	3.6	3.7	3.7	3.9	3.9
50	4	4	4	4.1	4.3	4.4	4.4	4.9	5.2	6
60	6.1	7.4	8.8	15						

		SUN	IMARY	STA	ГІЅТІС	cs			
	n			64					
	Mi			0					
	Ма	ıx				15			
	Ran			15					
	Me	an				2.878	1		
	Med	2.35							
	Varia	nce		5.3219					
	StdI	Dev		2.3069					
	Std E	rror		0.28836					
	Skew	ness				2.689	7		
Int	erquart	ile Raı	nge	2.425					
	Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	0.5825	0.63	1.425	2.35	3.85	5.05	7.075	15	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	5.23	3.218	Yes		

The test statistic 5.23 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	15

Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)								
Lilliefors Test Statistic	0.1022							
Lilliefors 5% Critical Value	0.1125							

The calculated Lilliefors test statistic is less than the 5% Lilliefors critical value, so the test cannot reject the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do appear to follow a normal distribution at the 5% level of significance.


Data Plots


Graphical displays of the data are shown below.


The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.







For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST							
Lilliefors Test Statistic	0.1453						
Lilliefors 5% Critical Value	0.1108						

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN						
95% Parametric UCL	3.36					
95% Non-Parametric (Chebyshev) UCL	4.135					

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (4.135) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=64 data, AL is the action level or threshold (81).

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=63 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic Critical Value $t_{0.95}$ Null Hypothesi							
-270.91	1.6694	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
64	39	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000. Software and documentation available at http://dqo.pnl.gov/vsp Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

^{* -} The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte		_				Para	ameter	
	Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
		21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL CEO	α=5		α=10		α=15		
AL=6521.2		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	2	2	1	1	1	1
LBGR=90	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
	β=5	2	2	1	1	1	1
LBGR=80	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
LBGR=70	β=5	2	2	1	1	1	1

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details	Per Analysis	Per Sample	21 Samples						
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

	SUMMARY STATISTICS								
	n				112				
	Mi	in				(0		
	Ma	ax				359	900		
	Rar	ige				359	900		
	Ме	an		5946.6					
	Med	lian			4265				
	Varia	nce		3.8705e+007					
	StdI	Dev		6221.3					
	Std E	Error				587	7.86		
	Skew	ness				2.5	682		
Inte	rquart	ile Raı	nge			556	67.5		
				Percentiles					
1%	5%	10%	25%	50%	75%	90%	95%	99%	
79.17	808.1	1128	2073	4265	7640	1.389e+004	1.679e+004	3.574e+004	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST									
k	Test Statistic R _k	5% Critical Value C _k	Significant?							
1	4.804	3.411	Yes							

The test statistic 4.804 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	35900

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)							
Lilliefors Test Statistic	0.22						
Lilliefors 5% Critical Value	0.08448						

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Lilliefors Test Statistic 0.2263						
Lilliefors 5% Critical Value	0.08372					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	6922			

95% Non-Parametric (Chebyshev) UCL 8509

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (8509) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data,AL is the action level or threshold (6521.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic Critical Value $t_{0.95}$ Null Hypothesis							
-0.9775	1.6587	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
82	65	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- 4. the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=8630.36		α=	α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	2	2	1	1	1	1	
LBGR=90	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
	β=5	2	2	1	1	1	1	
LBGR=80	β=10	2	2	1	1	1	1	
	β=15	2	2	1	1	1	1	
LBGR=70	β=5	2	2	1	1	1	1	

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details Per Analysis Per Sample 21 Sample									
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

	SUMMARY STATISTICS								
	n				112				
	Mi	in				(0		
	Ma	ax				359	900		
	Rar	ige				359	900		
	Ме	an				594	46.6		
	Med	lian		4265					
Variance					3.8705	5e+007			
	StdDev					622	21.3		
	Std E	Error				587	7.86		
Skewness					2.5	682			
Inte	rquart	ile Raı	nge			556	67.5		
Percentiles									
1%	5%	10%	25%	50% 75% 90% 95% 99%					
79.17	808.1	1128	2073	4265	7640	1.389e+004	1.679e+004	3.574e+004	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	4.815	3.414	Yes		

The test statistic 4.815 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS					
1	35900				

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.2158
Lilliefors 5% Critical Value	0.0841

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Lilliefors Test Statistic	0.2263					
Lilliefors 5% Critical Value	0.08372					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	6922				

95% Non-Parametric (Chebyshev) UCL 8509

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (8509) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data,
AL is the action level or threshold (8630.36),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value $t_{0.95}$	Null Hypothesis				
-4.5654	1.6587	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+)	95% Critical Value	Null Hypothesis					
87	65	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	109					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling ^d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL CEO	α=5		α=10		α=15		
AL=6521.2		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	2	2	1	1	1	1
LBGR=90	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
	β=5	2	2	1	1	1	1
LBGR=80	β=10	2	2	1	1	1	1
	β=15	2	2	1	1	1	1
LBGR=70	β=5	2	2	1	1	1	1

β=10	2	2	1	1	1	1
β=15	2	2	1	1	1	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

SUMMARY STATISTICS								
n				110				
Min				0				
Max				35900				
Range				35900				
Mean			5943.8					
Median			4265					
Variance			3.9239e+007					
StdDev			6264.1					
Std Error				597.26				
Skewness				2.5639				
Interquartile Range				5200				
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
66.99	804.7	1113	2060	4265	7260	1.403e+004	1.711e+004	3.577e+004

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	4.764	3.405	Yes		

The test statistic 4.764 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	35900	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.2191
Lilliefors 5% Critical Value	0.08526

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Lilliefors Test Statistic	0.2297		
Lilliefors 5% Critical Value	0.08448		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	6935

95% Non-Parametric (Chebyshev) UCL 8547

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (8547) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=110 data, AL is the action level or threshold (6521.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=109 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
-0.96678	1.659	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
81	64	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
A1 -0 -	70	α=5		α=10		α=15	
AL=9.	AL=9.79		s=3	s=6	s=3	s=6	s=3
	β=5	408	103	323	82	271	69
LBGR=90	β=10	324	82	248	63	203	51
	β=15	272	69	203	52	162	41
	β=5	103	27	82	21	69	18
LBGR=80	β=10	82	22	63	17	51	14
	β=15	69	19	52	14	41	11
LBGR=70	β=5	47	13	37	10	31	9

β=10	38	11	29	8	23	7
β=15	32	9	24	7	19	6

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

	SUMMARY					S		
	r	1				111		
	М	in				0		
	Ma	ax				17.3		
	Rar	nge				17.3		
Mean						1.866	4	
Median				1.3				
	Variance				4.868			
	StdDev				2.2064			
	Std E	Error		0.20942				
	Skew	ness		3.9354				
Inte	Interquartile Range				1.775			
	centiles							
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.0216	0.23	0.306	0.625	1.3	2.4	3.28	6.38	16.29

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER	'S OUTLIER TEST	
k	Test Statistic R _k	5% Critical Value C _k	Significant?
1	6.952	3.405	Yes

The test statistic 6.952 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS	
1	17.3

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.1794
Lilliefors 5% Critical Value	0.08526

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.2133				
Lilliefors 5% Critical Value	0.0841				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	2.214

95% Non-Parametric (Chebyshev) UCL 2.779

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.779) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=111 data, AL is the action level or threshold (9.79),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=110 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
-37.836	1.6588	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test					
Test Statistic (S+)	95% Critical Value	Null Hypothesis			
110	65	Reject			

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=9.79		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	408	103	323	82	271	69
LBGR=90	β=10	324	82	248	63	203	51
	β=15	272	69	203	52	162	41
	β=5	103	27	82	21	69	18
LBGR=80	β=10	82	22	63	17	51	14
	β=15	69	19	52	14	41	11
LBGR=70	β=5	47	13	37	10	31	9

β=10	38	11	29	8	23	7
β=15	32	9	24	7	19	6

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

	SUMMARY STATISTICS								
	n				112				
	N	/lin				0			
	N	l ax				17.3			
	Ra	nge				17.3			
	М	ean				1.878	3		
	Median					1.35			
	Var	iance		4.8401					
	Sto	dDev		2.2					
	Std	Error		0.20788					
	Ske	wness		3.9187					
Int	Interquartile Range					1.7662			
	entiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.0234	0.23	0.3065	0.6338	1.35	2.4	3.27	6.37	16.21	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

k	Test Statistic R _k	5% Critical Value C _k	Significant?
1	6.995	3.411	Yes

The test statistic 6.995 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	17.3

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outlier						
Lilliefors Test Statistic	0.1791					
Lilliefors 5% Critical Value	0.08448					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic 0.2111					
Lilliefors 5% Critical Value	0.08372				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	2.223

95% Non-Parametric (Chebyshev) UCL 2.784

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.784) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data, AL is the action level or threshold (9.79),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value $t_{0.95}$ Null Hypothesis					
-38.058	1.6587	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
111	65	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte		_				Para	ameter	
	Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
		21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples									
AL=0.39		α=	5	α=	10	α=15			
		s=6	s=3	s=6 s=3		s=6	s=3		
	β=5	256148	64038	202696	50675	170162	42541		
LBGR=90	β=10	202696	50676	155492	38874	127174	31794		
	β=15	170163	42542	127174	31795	101700	25426		
	β=5	64038	16011	50675	12670	42541	10636		
LBGR=80	β=10	50676	12670	38874	9720	31794	7949		
	β=15	42542	10637	31795	7950	25426	6357		
LBGR=70	β=5	28463	7117	22523	5632	18908	4728		

β=10	22523	5632	17278	4321	14131	3534
β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details Per Analysis Per Sample 21 Sample									
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

	SUMMARY STATISTICS								
		n				110			
	N	/lin				0			
	N	l ax				17.3			
	Ra	nge				17.3			
	М	ean				1.878	2		
	Median					1.35			
	Var	iance		4.8971					
	Sto	dDev		2.2129					
	Std	Error		0.211					
	Ske	wness		3.9224					
Int	erqua	rtile Rar	nge	1.7487					
			Perce	ntiles					
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0.0198	0.23	0.3055	0.6513	1.35	2.4	3.29	6.39	16.38	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?			
1	6.969	3.408	Yes			

The test statistic 6.969 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS					
1	17.3				

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding out					
Lilliefors Test Statistic	0.1786				
Lilliefors 5% Critical Value	0.08486				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST						
Lilliefors Test Statistic	0.2123					
Lilliefors 5% Critical Value	0.08448					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	2.228				

95% Non-Parametric (Chebyshev) UCL 2.798

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.798) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=110 data, AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=109 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
7.0532	1.659	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
16	64	Cannot Reject				

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	" [S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=2.50958		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	6188	1548	4897	1225	4111	1028
LBGR=90	β=10	4897	1226	3757	940	3072	769
	β=15	4111	1029	3073	769	2457	615
	β=5	1548	388	1225	307	1028	258
LBGR=80	β=10	1226	308	940	236	769	193
	β=15	1029	259	769	193	615	155
LBGR=70	β=5	689	174	545	137	458	115

β=10	546	138	419	106	342	86
β=15	458	116	343	87	274	69

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION							
Cost Details	Per Analysis	Per Sample	21 Samples				
Field collection costs		\$100.00	\$2,100.00				
Analytical costs	\$400.00	\$400.00	\$8,400.00				
Sum of Field & Analytical costs		\$500.00	\$10,500.00				
Fixed planning and validation costs			\$1,000.00				
Total cost			\$11,500.00				

Data Analysis

SUMMARY STATISTICS								
n			114					
	N	/lin		0				
	N	lax		17.3				
	Ra	inge		17.3				
Mean			1.9277					
Median			1.4					
Variance			5.0154					
StdDev			2.2395					
Std Error			0.20975					
	Skewness			3.6923				
I	Interquartile Range			1.7737				
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.2275	0.2975	0.6513	1.4	2.425	4	6.65	16.04

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST			
k	Test Statistic R _k	5% Critical Value C _k	Significant?
1	7.023	3.416	Yes

The test statistic 7.023 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS		
1	17.3	

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)		
Lilliefors Test Statistic	0.1715	
Lilliefors 5% Critical Value	0.08372	

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST		
Lilliefors Test Statistic	0.2081	
Lilliefors 5% Critical Value	0.08298	

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	2.276

95% Non-Parametric (Chebyshev) UCL 2.842

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.842) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=114 data,
AL is the action level or threshold (2.50958),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=113 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic Critical Value $t_{0.95}$ Null Hypothesis			
-2.774	1.6585	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test		
Test Statistic (S+) 95% Critical Value Null Hypothesi		
89	66	Reject

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.

SUMMARY OF SAMPLING DESIGN		
Primary Objective of Design	Compare a site mean to a fixed threshold	
Type of Sampling Design	Parametric	
Sample Placement (Location) in the Field	Simple random sampling	
Working (Null) Hypothesis	The mean value at the site exceeds the threshold	
Formula for calculating number of sampling locations	Student's t-test	
Calculated total number of samples	21	
Number of samples on map ^a	109	
Number of selected sample areas b	5	
Specified sampling area ^c	941426.62 m ²	
Total cost of sampling ^d	\$11,500.00	

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	Analyte n		Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=24.2		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	68	18	54	14	45	12
LBGR=90	β=10	54	15	42	11	34	9
	β=15	46	13	34	10	27	8
	β=5	18	6	14	5	12	4
LBGR=80	β=10	15	5	11	4	9	3
	β=15	13	5	10	3	8	3
LBGR=70	β=5	9	4	7	3	6	2

β=10	8	3	6	2	5	2
β=15	7	3	5	2	4	2

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

	SUMMARY STATISTICS								
n				111					
Min						0			
	M	ах				17.3			
	Ra	nge				17.3			
Mean						1.877	1		
	Median					1.3			
	Variance				4.8978				
	Std	Dev		2.2131					
	Std	Error		0.21006					
	Skev	ness		3.8834					
Interquartile Range				1.775					
Perd				centiles					
1%	5%	10%	25%	50%	75%	90%	95%	99%	
0	0.226	0.293	0.625	1.3	2.4	3.28	6.38	16.29	

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST					
k	Test Statistic R _k	5% Critical Value C _k	Significant?		
1	6.928	3.405	Yes		

The test statistic 6.928 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	17.3

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Lilliefors Test Statistic	0.1749			
Lilliefors 5% Critical Value	0.08526			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.2036			
Lilliefors 5% Critical Value	0.0841			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN				
95% Parametric UCL	2.226			

95% Non-Parametric (Chebyshev) UCL 2.793

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.793) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=111 data, AL is the action level or threshold (24.2),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=110 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value $t_{0.95}$ Null Hypothesis				
-106.27	1.6588	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
111	65	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
A1 -0 3			5	α=	10	α=15		
AL=0.39		s=6	s=3	s=6 s=3		s=6	s=3	
	β=5	256148	64038	202696	50675	170162	42541	
LBGR=90	β=10	202696	50676	155492	38874	127174	31794	
	β=15	170163	42542	127174	31795	101700	25426	
	β=5	64038	16011	50675	12670	42541	10636	
LBGR=80	β=10	50676	12670	38874	9720	31794	7949	
	β=15	42542	10637	31795	7950	25426	6357	
LBGR=70	β=5	28463	7117	22523	5632	18908	4728	

β=10	22523	5632	17278	4321	14131	3534
β=15	18909	4729	14132	3534	11301	2826

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

	SUMMARY STATISTICS							
	n)		109				
	Mi	in				0.09		
	Ма	ах				17.3		
	Rar	ige				17.21	l	
	Ме	an				1.893	8	
	Med	lian				1.4		
	Varia	nce		4.9227				
	StdI	Dev		2.2187				
	Std E	Error		0.21251				
	Skew	ness		3.9092				
Inte	Interquartile Range				1.735			
			Perc	centiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.0905	0.17	0.31	0.665	1.4	2.4	3.3	6.4	16.46

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	6.885	3.4	Yes				

The test statistic 6.885 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	17.3

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)				
Lilliefors Test Statistic	0.1759			
Lilliefors 5% Critical Value	0.08606			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic 0.213				
Lilliefors 5% Critical Value	0.08486			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE	MEAN
95% Parametric UCL	2.246

95% Non-Parametric (Chebyshev) UCL 2.82

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (2.82) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=109 data, AL is the action level or threshold (0.39),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=108 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value t _{0.95} Null Hypothesis					
7.0764	1.6591	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
15	64	Cannot Reject		

Note: There may not be enough data to reject the null hypothesis (and conclude site is clean) with 95% confidence using the MARSSIM sign test.

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
		α=	=5	α=	10	α=15		
AL=0.2	01	s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	571923	142982	452576	113145	379935	94985	
LBGR=90	β=10	452577	113146	347180	86796	283952	70989	
	β=15	379936	94985	283952	70989	227073	56769	
	β=5	142982	35747	113145	28287	94985	23747	
LBGR=80	β=10	113146	28288	86796	21700	70989	17748	
	β=15	94985	23748	70989	17748	56769	14193	
LBGR=70	β=5	63549	15889	50287	12573	42216	10555	

β=10	50288	12573	38577	9645	31551	7889
β=15	42217	10556	31551	7889	25231	6309

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

	SUMMARY STATISTICS							
n				113				
	Min					0		
	Max	K				3.97		
	Rang	ge				3.97		
	Mea	n			(0.18366	3	
	Median			0.079				
	Variance			0.18895				
StdDev			0.43469					
Std Error			0.040892					
	Skewn	ess		6.8685				
Inter	quartil	e Ran	ge	0.024				
Per				centile	es			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00868	0.068	0.07	0.074	0.079	0.098	0.374	0.726	3.704

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

	ROSNER'S OUTLIER TEST						
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	8.711	3.416	Yes				

The test statistic 8.711 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Lilliefors Test Statistic	0.3975				
Lilliefors 5% Critical Value	0.08372				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4224			
Lilliefors 5% Critical Value	0.08335			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	0.2515

95% Non-Parametric (Chebyshev) UCL 0.3619

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.3619) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=113 data, AL is the action level or threshold (0.261),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=112 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic Critical Value t _{0.95} Null Hypothesis				
-1.8912	1.6586	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
101	66	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=0.261		α=	=5	α=	10	α=15		
		s=6	s=3	s=6 s=3		s=6	s=3	
	β=5	571923	142982	452576	113145	379935	94985	
LBGR=90	β=10	452577	113146	347180	86796	283952	70989	
	β=15	379936	94985	283952	70989	227073	56769	
	β=5	142982	35747	113145	28287	94985	23747	
LBGR=80	β=10	113146	28288	86796	21700	70989	17748	
	β=15	94985	23748	70989	17748	56769	14193	
LBGR=70	β=5	63549	15889	50287	12573	42216	10555	

β=10	50288	12573	38577	9645	31551	7889
β=15	42217	10556	31551	7889	25231	6309

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

		SU	MMAR	Y STATI	STICS			
n				112				
	Mi	n			0			
	Ма	ıx				3.97		
	Ran	ge				3.97		
	Me	an			0.	18468		
	Med	ian		0.07925				
	Varia	nce		0.19054				
	StdI	Dev		0.43651				
	Std E	rror		0.041246				
	Skew	ness		6.8383				
Inte	rquarti	ile Rang	je		(0.024		
Pe				rcentiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00806	0.068	0.0703	0.074	0.07925	0.098	0.383	0.727	3.723

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST				
k	Test Statistic R _k	5% Critical Value C _k	Significant?	
1	8.672	3.414	Yes	

The test statistic 8.672 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)					
Lilliefors Test Statistic	0.3978				
Lilliefors 5% Critical Value	0.0841				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST				
Lilliefors Test Statistic	0.4222			
Lilliefors 5% Critical Value	0.08372			

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	0.2531

95% Non-Parametric (Chebyshev) UCL 0.3645

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.3645) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data, AL is the action level or threshold (0.261),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Null Hypothesis			
-1.8504	1.6587	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test			
Test Statistic (S+) 95% Critical Value Null Hypothesis			
100	65	Reject	

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=0.1		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	3895984	973997	3082986	770748	2588149	647038
LBGR=90	β=10	3082987	770748	2365020	591256	1934301	483576
	β=15	2588150	647039	1934301	483576	1546841	386711
	β=5	973997	243501	770748	192688	647038	161760
LBGR=80	β=10	770748	192688	591256	147815	483576	120895
	β=15	647039	161761	483576	120895	386711	96679
LBGR=70	β=5	432889	108224	342555	85640	287573	71894

β=10	342556	85640	262781	65696	214923	53732
β=15	287574	71895	214923	53732	171872	42969

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

		SU	MMAR	Y STATIS	STICS			
n				110				
	Min	1				0		
	Мах	ζ			;	3.97		
	Rang	je			;	3.97		
Mean					0.	18668		
	Median			0.07925				
	Varian	ice		0.1938				
	StdDe	ev		0.44023				
	Std Er	ror		0.041974				
	Skewn	ess		6.7771				
Int	Interquartile Range				0.	0245		
		centiles						
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00682	0.06855	0.0711	0.074	0.07925	0.0985	0.401	0.729	3.761

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST				
k	Test Statistic R _k	5% Critical Value C _k	Significant?	
1	8.569	3.405	Yes	

The test statistic 8.569 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.4027
Lilliefors 5% Critical Value	0.08526

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Lilliefors Test Statistic	0.4219		
Lilliefors 5% Critical Value	0.08448		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	0.2563

95% Non-Parametric (Chebyshev) UCL 0.3696

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.3696) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=110 data, AL is the action level or threshold (0.1),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=109 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST				
t-statistic	Critical Value t _{0.95}	Null Hypothesis		
2.0651	1.659	Reject		

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+)	95% Critical Value	Null Hypothesis		
83	63	Reject		

This report was automatically produced * by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_				Para	ameter	
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
A1 _0 07	74 5 4	α=5		α=10		α=15	
AL=0.07	AL=8.87154		s=3	s=6	s=3	s=6	s=3
	β=5	497	126	393	99	330	83
LBGR=90	β=10	394	100	302	76	247	62
	β=15	331	84	247	63	198	50
	β=5	126	33	99	26	83	22
LBGR=80	β=10	100	26	76	20	62	16
	β=15	84	22	63	17	50	13
LBGR=70	β=5	57	16	45	12	38	10

β=10	45	13	35	10	28	8
β=15	38	11	29	8	23	6

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION						
Cost Details	Per Analysis	Per Sample	21 Samples			
Field collection costs		\$100.00	\$2,100.00			
Analytical costs	\$400.00	\$400.00	\$8,400.00			
Sum of Field & Analytical costs		\$500.00	\$10,500.00			
Fixed planning and validation costs			\$1,000.00			
Total cost			\$11,500.00			

Data Analysis

		SU	MMAR	Y STATI	STICS			
	n					112		
	Mi	n				0		
	Ма	ıx				3.97		
	Ran	ge				3.97		
Mean					0.	18468		
Median					0.	07925		
	Variance				0.19054			
	StdDev				0.43651			
	Std E	rror		0.041246				
	Skew	ness		6.8383				
Inte	Interquartile Range				0.024			
			rcentiles					
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00806	0.068	0.0703	0.074	0.07925	0.098	0.383	0.727	3.723

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST			
k	Test Statistic R _k	5% Critical Value C _k	Significant?
1	8.633	3.411	Yes

The test statistic 8.633 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS	
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)
Lilliefors Test Statistic	0.3982
Lilliefors 5% Critical Value	0.08448

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic	0.4222				
Lilliefors 5% Critical Value	0.08372				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	0.2531

95% Non-Parametric (Chebyshev) UCL 0.3645

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.3645) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data,
AL is the action level or threshold (8.87154),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST						
t-statistic	Critical Value t _{0.95}	Null Hypothesis				
-210.61	1.6587	Reject				

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
112	65	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyto		_				Para	ameter	
	Analyte	∌∥n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
		21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=5.6		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	1244	312	984	247	826	207
LBGR=90	β=10	985	248	755	190	618	155
	β=15	827	208	618	156	494	124
	β=5	312	79	247	63	207	53
LBGR=80	β=10	248	63	190	48	155	40
	β=15	208	53	156	40	124	32
LBGR=70	β=5	140	36	111	29	93	24

β=10	111	29	85	22	70	18
β=15	94	25	70	18	56	15

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION								
Cost Details	Per Analysis	Per Sample	21 Samples					
Field collection costs		\$100.00	\$2,100.00					
Analytical costs	\$400.00	\$400.00	\$8,400.00					
Sum of Field & Analytical costs		\$500.00	\$10,500.00					
Fixed planning and validation costs			\$1,000.00					
Total cost			\$11,500.00					

Data Analysis

SUMMARY STATISTICS								
n						110		
	Min					0		
	Max	((3.97		
	Rang	je			(3.97		
Mean					0.	18668		
Median				0.07925				
	Variance				0.1938			
	StdD	ev		0.44023				
	Std Er	ror		0.041974				
	Skewn	ess		6.7771				
Int	Interquartile Range				0.0245			
Per				centiles				
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.00682	0.06855	0.0711	0.074	0.07925	0.0985	0.401	0.729	3.761

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
	k	Test Statistic R _k	5% Critical Value C _k	Significant?			
	1	8.594	3.408	Yes			

The test statistic 8.594 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTE	OUTLIERS
1	3.97

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)						
Lilliefors Test Statistic	0.3982					
Lilliefors 5% Critical Value	0.08486					

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST					
Lilliefors Test Statistic 0.4219					
Lilliefors 5% Critical Value	0.08448				

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE I	MEAN
95% Parametric UCL	0.2563

95% Non-Parametric (Chebyshev) UCL 0.3696

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (0.3696) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\bar{x} - AL}{SE}$$

where

x is the sample mean of the n=110 data, AL is the action level or threshold (5.6),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=109 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST					
t-statistic Critical Value t _{0.95} Null Hypothesis					
-128.97	1.659	Reject			

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test							
Test Statistic (S+) 95% Critical Value Null Hypothesis							
110	64	Reject					

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SAMPLING DESIGN
Primary Objective of Design	Compare a site mean to a fixed threshold
Type of Sampling Design	Parametric
Sample Placement (Location) in the Field	Simple random sampling
Working (Null) Hypothesis	The mean value at the site exceeds the threshold
Formula for calculating number of sampling locations	Student's t-test
Calculated total number of samples	21
Number of samples on map ^a	109
Number of selected sample areas b	5
Specified sampling area ^c	941426.62 m ²
Total cost of sampling ^d	\$11,500.00

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analyte		_				Para	ameter	
	Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
		21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples								
AL=43.4		α=5		α=10		α=15		
		s=6	s=3	s=6	s=3	s=6	s=3	
	β=5	23	7	18	5	15	4	
LBGR=90	β=10	18	6	14	4	11	4	
	β=15	16	5	12	4	9	3	
	β=5	7	3	5	2	4	2	
LBGR=80	β=10	6	3	4	2	4	2	
	β=15	5	3	4	2	3	2	
LBGR=70	β=5	4	2	3	2	3	1	

β=10	4	2	3	2	2	1
β=15	3	2	2	2	2	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION									
Cost Details Per Analysis Per Sample 21 Sample									
Field collection costs		\$100.00	\$2,100.00						
Analytical costs	\$400.00	\$400.00	\$8,400.00						
Sum of Field & Analytical costs		\$500.00	\$10,500.00						
Fixed planning and validation costs			\$1,000.00						
Total cost			\$11,500.00						

Data Analysis

SUMMARY STATISTICS								
	n			110				
	Mir	า				0		
	Ma	X				270		
	Ran	ge				270		
	Mea	ın				7.821	9	
	3.8							
	Varia	nce		664.6				
	StdD	ev		25.78				
	Std E	rror		2.458				
	Skewr	ness		9.8371				
Inter	quartil	le Ran	ge	4.95				
			Perc	entile	s			
1%	5%	10%	25%	50%	75%	90%	95%	99%
0.05555	1.019	1.305	2.075	3.8	7.025	13.2	16.25	243.6

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST							
k	Test Statistic R _k	5% Critical Value C _k	Significant?				
1	10.12	3.405	Yes				

The test statistic 10.12 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS					
1	270				

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION	TEST (excluding outliers)		
Lilliefors Test Statistic	0.2254		
Lilliefors 5% Critical Value	0.08526		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST							
Lilliefors Test Statistic	0.3808						
Lilliefors 5% Critical Value	0.08448						

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN					
95% Parametric UCL	11.9				

95% Non-Parametric (Chebyshev) UCL	18.54

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (18.54) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=110 data, AL is the action level or threshold (43.4),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=109 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST							
t-statistic	Critical Value t _{0.95}	Null Hypothesis					
-14.474	1.659	Reject					

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test						
Test Statistic (S+)	95% Critical Value	Null Hypothesis				
109	64	Reject				

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

* - The report contents may have been modified or reformatted by end-user of software.

Random sampling locations for comparing a mean with a fixed threshold (parametric)

Summary

This report summarizes the sampling design used, associated statistical assumptions, as well as general guidelines for conducting post-sampling data analysis. Sampling plan components presented here include how many sampling locations to choose and where within the sampling area to collect those samples. The type of medium to sample (i.e., soil, groundwater, etc.) and how to analyze the samples (in-situ, fixed laboratory, etc.) are addressed in other sections of the sampling plan.

The following table summarizes the sampling design developed. A figure that shows sampling locations in the field is also provided below.


SUMMARY OF	SUMMARY OF SAMPLING DESIGN					
Primary Objective of Design	Compare a site mean to a fixed threshold					
Type of Sampling Design	Parametric					
Sample Placement (Location) in the Field	Simple random sampling					
Working (Null) Hypothesis	The mean value at the site exceeds the threshold					
Formula for calculating number of sampling locations	Student's t-test					
Calculated total number of samples	21					
Number of samples on map ^a	109					
Number of selected sample areas b	5					
Specified sampling area ^c	941426.62 m ²					
Total cost of sampling ^d	\$11,500.00					

^a This number may differ from the calculated number because of 1) grid edge effects, 2) adding judgment samples, or 3) selecting or unselecting sample areas.

^b The number of selected sample areas is the number of colored areas on the map of the site. These sample areas contain the locations where samples are collected.

^c The sampling area is the total surface area of the selected colored sample areas on the map of the site.

^d Including measurement analyses and fixed overhead costs. See the Cost of Sampling section for an explanation of the costs presented here.



Primary Sampling Objective

The primary purpose of sampling at this site is to compare a mean value with a fixed threshold. The working hypothesis (or 'null' hypothesis) is that the mean value at the site is equal to or exceeds the threshold. The alternative hypothesis is that the mean value is less than the threshold. VSP calculates the number of samples required to reject the null hypothesis in favor of the alternative hypothesis, given a selected sampling approach and inputs to the associated equation.

Selected Sampling Approach

A parametric random sampling approach was used to determine the number of samples and to specify sampling locations. A parametric formula was chosen because the conceptual model and historical information (e.g., historical data from this site or a very similar site) indicate that parametric assumptions are reasonable. These assumptions will be examined in post-sampling data analysis.

Both parametric and non-parametric approaches rely on assumptions about the population. However, non-parametric approaches typically require fewer assumptions and allow for more uncertainty about the statistical distribution of values at the site. The trade-off is that if the parametric assumptions are valid, the required number of samples is usually less than the number of samples required by non-parametric approaches.

Locating the sample points randomly provides data that are separated by many distances, whereas systematic samples are all equidistant apart. Therefore, random sampling provides more information about the spatial structure of the potential contamination than systematic sampling does. As with systematic sampling, random sampling also provides information regarding the mean value, but there is the possibility that areas of the site will not be represented with the same frequency as if uniform grid sampling were performed.

Number of Total Samples: Calculation Equation and Inputs

The equation used to calculate the number of samples is based on a Student's t-test. For this site, the null hypothesis is rejected in favor of the alternative hypothesis if the sample mean is sufficiently smaller than the threshold. The number of

samples to collect is calculated so that 1) there will be a high probability $(1-\beta)$ of rejecting the null hypothesis if the alternative hypothesis is true and 2) a low probability (α) of rejecting the null hypothesis if the null hypothesis is true.

The formula used to calculate the number of samples is:

$$n = \frac{S^2}{\Delta^2} \left(Z_{1-\alpha} + Z_{1-\beta} \right)^2 + 0.5 Z_{1-\alpha}^2$$

where

n is the number of samples,

S is the estimated standard deviation of the measured values including analytical error,

 Δ is the width of the gray region,

 α is the acceptable probability of incorrectly concluding the site mean is less than the threshold,

β is the acceptable probability of incorrectly concluding the site mean exceeds the threshold,

is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α , is the value of the standard normal distribution such that the proportion of the distribution less than $Z_{1-\alpha}$ is 1- α .

The values of these inputs that result in the calculated number of sampling locations are:

Analysta	_	Parameter					
Analyte	n	S	Δ	α	β	Z _{1-α} a	Z _{1-β} b
	21	3	2	0.05	0.1	1.64485	1.28155


^a This value is automatically calculated by VSP based upon the user defined value of α .

b This value is automatically calculated by VSP based upon the user defined value of β.

The following figure is a performance goal diagram, described in EPA's QA/G-4 guidance (EPA, 2000). It shows the probability of concluding the sample area is dirty on the vertical axis versus a range of possible true mean values for the site on the horizontal axis. This graph contains all of the inputs to the number of samples equation and pictorially represents the calculation.

The red vertical line is shown at the threshold (action limit) on the horizontal axis. The width of the gray shaded area is equal to Δ ; the upper horizontal dashed blue line is positioned at 1- α on the vertical axis; the lower horizontal dashed blue line is positioned at β on the vertical axis. The vertical green line is positioned at one standard deviation below the threshold. The shape of the red curve corresponds to the estimates of variability. The calculated number of samples results in the curve that passes through the lower bound of Δ at β and the upper bound of Δ at 1- α . If any of the inputs change, the number of samples that result in the correct curve changes.

1-Sample t-Test of True Mean vs. Action Level



Statistical Assumptions

The assumptions associated with the formulas for computing the number of samples are:

- 1. the sample mean is normally distributed (this happens if the data are roughly symmetric and the sample size is 30 or more; for skewed data sets, additional samples are required for the sample mean to be normally distributed),
- 2. the variance estimate, S^2 , is reasonable and representative of the population being sampled,
- 3. the population values are not spatially or temporally correlated, and
- the sampling locations will be selected randomly.

The first three assumptions will be assessed in a post data collection analysis. The last assumption is valid because the sample locations were selected using a random process.

Sensitivity Analysis

The sensitivity of the calculation of number of samples was explored by varying the standard deviation, lower bound of gray region (% of action level), beta (%), probability of mistakenly concluding that μ > action level and alpha (%), probability of mistakenly concluding that μ < action level and examining the resulting changes in the number of samples. The following table shows the results of this analysis.

Number of Samples							
AL=43.4		α=5		α=10		α=15	
		s=6	s=3	s=6	s=3	s=6	s=3
	β=5	23	7	18	5	15	4
LBGR=90	β=10	18	6	14	4	11	4
	β=15	16	5	12	4	9	3
	β=5	7	3	5	2	4	2
LBGR=80	β=10	6	3	4	2	4	2
	β=15	5	3	4	2	3	2
LBGR=70	β=5	4	2	3	2	3	1

β=10	4	2	3	2	2	1
β=15	3	2	2	2	2	1

s = Standard Deviation

LBGR = Lower Bound of Gray Region (% of Action Level)

 β = Beta (%), Probability of mistakenly concluding that μ > action level

 α = Alpha (%), Probability of mistakenly concluding that μ < action level

AL = Action Level (Threshold)

Cost of Sampling

The total cost of the completed sampling program depends on several cost inputs, some of which are fixed, and others that are based on the number of samples collected and measured. Based on the numbers of samples determined above, the estimated total cost of sampling and analysis at this site is \$11,500.00, which averages out to a per sample cost of \$547.62. The following table summarizes the inputs and resulting cost estimates.

COST INFORMATION					
Cost Details	Per Analysis	Per Sample	21 Samples		
Field collection costs		\$100.00	\$2,100.00		
Analytical costs	\$400.00	\$400.00	\$8,400.00		
Sum of Field & Analytical costs		\$500.00	\$10,500.00		
Fixed planning and validation costs			\$1,000.00		
Total cost			\$11,500.00		

Data Analysis

SUMMARY STATISTICS								
n		112						
	Min					0		
	М	ах				270		
	Rai	nge		270				
	Мє	ean		7.7916				
	Median		3.8					
Variance			653.35					
	StdDev		25.561					
Std Error			2.4153					
Skewness			9.9105					
Interquartile Range			5.25					
Percentiles								
1%	5%	10%	25%	50%	75%	90%	95%	99%
0	0.913	1.265	2.025	3.8	7.275	12.99	16.03	238.8

Outlier Test

Rosner's test for multiple outliers was performed to test whether the most extreme value is a statistical outlier. The test was conducted at the 5% significance level.

Data should not be excluded from analysis solely on the basis of the results of this or any other statistical test. If any

values are flagged as possible outliers, further investigation is recommended to determine whether there is a plausible explanation that justifies removing or replacing them.

In using Rosner's test to detect up to 1 outlier, a test statistic R_1 is calculated, and compared with a critical value C_1 to test the hypothesis that there is one outlier in the data.

ROSNER'S OUTLIER TEST				
k Test Statistic R _k 5% Critical Value C _k Significant				
1	10.21	3.411	Yes	

The test statistic 10.21 exceeded the corresponding critical value, therefore that test is significant and we conclude that the most extreme value is an outlier at the 5% significance level.

SUSPECTED OUTLIERS			
1	270		

A normal distribution test indicated that the data do not appear to be normally distributed, so further investigation is recommended before using the results of this test. Because Rosner's test can be used only when the data without the suspected outlier are approximately normally distributed, a Lilliefors test for normality was performed at a 5% significance level.

NORMAL DISTRIBUTION TEST (excluding outliers)			
Lilliefors Test Statistic 0.2245			
Lilliefors 5% Critical Value	0.08448		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so the test rejects the hypothesis that the data are normal and concludes that the data, excluding the most extreme value, do not appear to follow a normal distribution at the 5% level of significance. Rosner's test may not be appropriate if the assumption of normally distributed data is not justified for this data set. Examine the Q-Q plot displayed below to further assess the normality of the data.


Data Plots

Graphical displays of the data are shown below.

The Histogram is a plot of the fraction of the n observed data that fall within specified data "bins." A histogram is generated by dividing the x axis (range of the observed data values) into "bins" and displaying the number of data in each bin as the height of a bar for the bin. The area of the bar is the fraction of the n data values that lie within the bin. The sum of the fractions for all bins equals one. A histogram is used to assess how the n data are distributed (spread) over their range of values. If the histogram is more or less symmetric and bell shaped, then the data may be normally distributed.

The Box and Whiskers plot is composed of a central box divided by a line, and with two lines extending out from the box, called the "whiskers". The line through the box is drawn at the median of the n data observed. The two ends of the box represent the 25th and 75th percentiles of the n data values, which are also called the lower and upper quartiles, respectively, of the data set. The sample mean (mean of the n data) is shown as a "+" sign. The upper whisker extends to the largest data value that is less than the upper quartile plus 1.5 times the interquartile range (upper quartile minus the lower quartile). The lower whisker extends to the smallest data value that is greater than the lower quartile minus 1.5 times the interquartile range. Extreme data values (greater or smaller than the ends of the whiskers) are plotted individually as blue Xs. A Box and Whiskers plot is used to assess the symmetry of the distribution of the data set. If the distribution is symmetrical, the box is divided into two equal halves by the median, the whiskers will be the same length, and the number of extreme data points will be distributed equally on either end of the plot.

The Q-Q plot graphs the quantiles of a set of n data against the quantiles of a specific distribution. We show here only the Q-Q plot for an assumed normal distribution. The p^{th} quantile of a distribution of data is the data value, x_n , for which a fraction p of the distribution is less than x_n . If the data plotted on the normal distribution Q-Q plot closely follow a straight line, even at the ends of the line, then the data may be assumed to be normally distributed. If the data points deviate substantially from a linear line, then the data are not normally distributed.



For more information on these plots consult Guidance for Data Quality Assessment, EPA QA/G-9, pgs 2.3-1 through 2.3-12. (http://www.epa.gov/quality/qa-docs.html).

Tests

A goodness-of-fit test was performed to test whether the data set had been drawn from an underlying normal distribution. The Lilliefors test was used to test the null hypothesis that the data are normally distributed. The test was conducted at the 5% significance level, i.e., the probability the test incorrectly rejects the null hypothesis was set at 0.05.

NORMAL DISTRIBUTION TEST			
Lilliefors Test Statistic 0.3802			
Lilliefors 5% Critical Value	0.08372		

The calculated Lilliefors test statistic exceeds the 5% Lilliefors critical value, so we can reject the hypothesis that the data are normal, or in other words the data do not appear to follow a normal distribution at the 5% level of significance. The Q-Q plot displayed above should be used to further assess the normality of the data.

Upper Confidence Limit on the True Mean

Two methods were used to compute the upper confidence limit (UCL) on the mean. The first is a parametric method that assumes a normal distribution. The second is the Chebyshev method, which requires no distributional assumption.

UCLs ON THE MEAN		
95% Parametric UCL	11.8	

Because the data do not appear to be normally distributed according to the goodness-of-fit test performed above, the non-parametric UCL (18.32) may be a more accurate upper confidence limit on the true mean.

One-Sample t-Test

A one-sample t-test was performed to compare the sample mean to the action level. The null hypothesis used is that the true mean equals or exceeds the action level (AL). The t-test was conducted at the 5% significance level. The sample value *t* was computed using the following equation:

$$t = \frac{\overline{x} - AL}{SE}$$

where

x is the sample mean of the n=112 data, AL is the action level or threshold (43.4),

SE is the standard error = (standard deviation) / (square root of n).

This t was then compared with the critical value $t_{0.95}$, where $t_{0.95}$ is the value of the t distribution with n-1=111 degrees of freedom for which the proportion of the distribution to the left of $t_{0.95}$ is 0.95. The null hypothesis will be rejected if $t < -t_{0.95}$.

ONE-SAMPLE t-TEST			
t-statistic Critical Value $t_{0.95}$ Null Hypothesis			
-14.743	1.6587	Reject	

The test rejected the null hypothesis that the mean value at the site exceeds the threshold, therefore conclude the true mean is less than the threshold.

Because the data do not appear to be normally distributed, the MARSSIM Sign Test might be preferred over the One Sample t-Test. The following table represents the results of the MARSSIM Sign Test using the current data:

MARSSIM Sign Test				
Test Statistic (S+) 95% Critical Value Null Hypothesis				
111	65	Reject		

This report was automatically produced* by Visual Sample Plan (VSP) software version 5.000.

Software and documentation available at http://dqo.pnl.gov/vsp

Software copyright (c) 2008 Battelle Memorial Institute. All rights reserved.

 $\ensuremath{^{*}}$ - The report contents may have been modified or reformatted by end-user of software.